

# Unit Job History

Michels Corporation  
Report Printed: 08-Apr-2019 04:18:13 By User: RHENNING

| WO Open Date                          | Meter 1 | Meter 2 | Work Order | Job Code    | Job Description                        | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|---------------------------------------|---------|---------|------------|-------------|--|----------------------|--------------|------------|------------|------------|
| Unit No: E1012 - 2011 JOHN DEERE 320D |         |         |            |             |  |                      |              |            |            |            |
| 24-Feb-2012 11:18:11                  | 1       | 0       | 82303      | 12-514      | Refinish Bucket                        | 05-Mar-2012 08:56:27 | BBODY        | C          | DON        | 50.15      |
| 17-Aug-2017 07:37:11                  | 1       | 0       | 82303      | 21-514      | Fabricate Bucket                       | 03-Mar-2012 08:26:16 | BWELD        | C          | DON        | 2,692.72   |
| 17-Aug-2017 07:37:11                  | 3,840   | 0       | 301433     | 03-013-030  | Replace Switch - Parking Brake         | 21-Aug-2017 17:01:20 | BBKHOE       | I          | DON        | 48.69      |
| 17-Aug-2017 07:37:11                  | 3,840   | 0       | 301433     | 03-031-001  | Replace Generator/Alternator           | 21-Aug-2017 16:21:11 | BBKHOE       | I          | DON        | 498.11     |
| 23-Apr-2015 07:52:11                  | 2,280   | 0       | 301433     | 03-360-004  | Replace Final Drive                    | 17-Aug-2017 09:35:52 | BBKHOE       | B          | DON        | 166.01     |
| 09-Nov-2015 13:36:00                  | 2,280   | 0       | 198713     | 03-020      | Replace Drivetrain Group               | 09-Jun-2015 10:03:12 | BSMEQP       | B          | DON        | 3,245.27   |
| 07-Oct-2014 16:39:52                  | 1,745   | 0       | 221345     | 03-031-006  | Replace Belt - Alternator              | 09-Nov-2015 15:22:59 | BSMEQP       | F          | DON        | 280.67     |
| 31-Aug-2017 10:09:33                  | 3,841   | 0       | 175083     | 03-360-004  | Replace Final Drive                    | 07-Oct-2014 16:48:09 | BSMEQP       | O          | DON        | 1,978.91   |
| 31-Aug-2017 10:09:33                  | 3,841   | 0       | 303266     | 03-032-002  | Replace Starter                        | 05-Sep-2017 10:45:20 | BBKHOE       | B          | DON        | 332.51     |
| 31-Aug-2017 10:09:33                  | 3,841   | 0       | 303266     | 03-065-008  | Replace Line / Tubing Assembly         | 06-Sep-2017 09:42:13 | BBKHOE       | B          | DON        | 314.62     |
| 10-Nov-2015 10:01:55                  | 2,779   | 0       | 303266     | 06-100-PM/A | Inspect A PMI                          | 06-Sep-2017 10:22:17 | BBKHOE       | P          | DON        | 262.34     |
| 10-Nov-2015 10:01:55                  | 2,779   | 0       | 221472     | 02-360      | Clean Loader / Skid-Steer              | 10-Nov-2015 14:06:00 | BWASH        | J          | DON        | 54.70      |
| 10-Nov-2015 10:01:55                  | 2,779   | 0       | 221472     | 03-032-001  | Replace Battery                        | 10-Nov-2015 16:15:56 | BSMEQP       | O          | DON        | 122.70     |
| 10-Nov-2015 10:01:55                  | 2,779   | 0       | 221472     | 03-042-004  | Replace Water Pump                     | 10-Nov-2015 16:15:49 | BSMEQP       | I          | DON        | 402.47     |
| 31-Aug-2017 14:00:22                  | 3,840   | 0       | 303372     | 02-360      | Clean Loader / Skid-Steer              | 31-Aug-2017 17:00:09 | BWASH        | J          | DON        | 226.08     |
| 19-Nov-2018 11:49:11                  | 4,938   | 0       | 361176     | 02-002      | Clean Cab & Sheet Metal                | 03-Dec-2018 14:42:14 | BSETUP       | I          | DON        | 31.02      |
| 19-Nov-2018 11:49:11                  | 4,938   | 0       | 361176     | 03-032-001  | Replace Battery                        | 03-Dec-2018 12:00:19 | BBKHOE       | I          | DON        | 118.05     |
| 19-Nov-2018 11:49:11                  | 4,938   | 0       | 361176     | 03-032-002  | Replace Starter                        | 03-Dec-2018 10:00:22 | BBKHOE       | O          | DON        | 326.55     |
| 19-Nov-2018 11:49:11                  | 4,938   | 0       | 361176     | 03-065-004  | Replace Cylinder                       | 03-Dec-2018 07:41:23 | BBKHOE       | P          | DON        | 1,459.35   |
| 19-Nov-2018 11:49:11                  | 4,938   | 0       | 361176     | 06-100-PM/A | Inspect A PMI                          | 11-Dec-2018 12:47:01 | BBKHOE       | P          | DON        | 536.39     |
| 19-Nov-2018 11:49:11                  | 4,938   | 0       | 361176     | 24-063-003  | Repair Transceiver - GPS Tracker       | 03-Dec-2018 11:05:53 | BBKHOE       | Q          | DON        | 33.20      |
| 19-Nov-2018 11:49:11                  | 4,938   | 0       | 361176     | 24-514      | Repair Bucket                          | 05-Dec-2018 11:04:37 | BWELD        | N          | DON        | 416.16     |
| 15-Nov-2011 14:49:33                  | 1       | 0       | 76620      | 31-017-005  | Rotate Tire - Solid                    | 30-Nov-2018 09:44:44 | BBKHOE       | Q          | DON        | 27.71      |
| 15-Nov-2011 14:49:33                  | 1       | 0       | 76620      | 06-100-001  | Inspect DO NOT USE - PMI Service       | 17-Nov-2011 13:08:58 | BSMEQP       | J          | DON        | 29.03      |
| 03-Jan-2013 07:14:52                  | 770     | 0       | 103656     | 14-063-003  | Install Transceiver - GPS Tracker      | 17-Nov-2011 13:08:58 | BSMEQP       | J          | DON        | 351.84     |
| 03-Jan-2013 07:14:52                  | 770     | 0       | 103656     | 02-360      | Clean Loader / Skid-Steer              | 09-Jan-2013 09:00:00 | BWASH        | J          | DON        | 81.29      |
| 03-Jan-2013 07:14:52                  | 770     | 0       | 103656     | 24-034-006  | Repair Warning Lamps - Special Applica | 11-Jan-2013 09:00:00 | BSMEQP       | I          | DON        | 125.94     |
| 03-Jan-2013 07:14:52                  | 770     | 0       | 103656     | 38-100-001  | Service DO NOT USE - PMI Service       | 14-Jan-2013 10:49:03 | BSMEQP       | J          | DON        | 752.96     |

# Unit Job History

Michels Corporation  
Report Printed: 08-Apr-2019 04:18:13 By User: RHEVENING

| WO Open Date                                 | Meter 1 | Meter 2 | Work Order | Job Code    | Job Description                        | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|-------------|--|----------------------|--------------|------------|------------|------------|
| <b>Unit No: E1012 - 2011 JOHN DEERE 320D</b> |         |         |            |             |  |                      |              |            |            |            |
| 09-Nov-2016 12:37:5                          | 3,385   | 0       | 266077     | 02-360      | Clean Loader / Skid-Steer              | 09-Nov-2016 14:39:45 | BKHOE        | I          | DON        | 48.06      |
| 09-Nov-2016 12:37:5                          | 3,385   | 0       | 266077     | 03-017-003  | Replace Tire - Cushion                 | 09-Nov-2016 14:34:17 | BTIRE        | I          | DON        | 4,538.64   |
| 09-Nov-2016 12:37:5                          | 3,385   | 0       | 266077     | 06-100-PMIA | Inspect A PMI                          | 09-Nov-2016 17:00:02 | BKHOE        | P          | DON        | 144.29     |
| 09-Mar-2015 14:30:4                          | 2,205   | 0       | 193963     | 02-360      | Clean Loader / Skid-Steer              | 11-Mar-2015 16:23:21 | BWASH        | J          | DON        | 89.83      |
| 09-Mar-2015 14:30:4                          | 2,205   | 0       | 193963     | 03-017-005  | Replace Tire - Solid                   | 20-Mar-2015 09:19:02 | BSMEQP       | I          | DON        | 1,836.60   |
| 09-Mar-2015 14:30:4                          | 2,205   | 0       | 193963     | 03-065-004  | Replace Cylinder                       | 20-Mar-2015 09:19:35 | BSMEQP       | I          | DON        | 1,204.07   |
| 09-Mar-2015 14:30:4                          | 2,205   | 0       | 193963     | 03-360-004  | Replace Final Drive                    | 20-Mar-2015 09:19:24 | BSMEQP       | I          | DON        | 493.29     |
| 09-Mar-2015 14:30:4                          | 2,205   | 0       | 193963     | 06-030      | Inspect Electrical Group               | 20-Mar-2015 09:19:17 | BSMEQP       | I          | DON        | 203.46     |
| 09-Mar-2015 14:30:4                          | 2,205   | 0       | 193963     | 06-360-011  | Inspect Quick-Attach Coupling Assembly | 20-Mar-2015 09:19:08 | BSMEQP       | J          | DON        | 393.35     |
| 09-Mar-2015 14:30:4                          | 2,205   | 0       | 193963     | 38-040      | Service Engine / Motor Systems Group   | 20-Mar-2015 09:18:55 | BSMEQP       | J          | DON        | 707.21     |
| 02-Feb-2016 06:46:22                         | 2,779   | 0       | 231728     | 02-360      | Clean Loader / Skid-Steer              | 02-Feb-2016 11:07:18 | BWASH        | J          | DON        | 100.11     |
| 17-Apr-2017 13:32:0                          | 3,840   | 0       | 285445     | 03-013-034  | Replace Parking Brake - Complete       | 21-Apr-2017 11:01:52 | BKHOE        | B          | DON        | 3,620.36   |
| 17-Apr-2017 13:32:0                          | 3,840   | 0       | 285445     | 06-100-PMIA | Inspect A PMI                          | 21-Apr-2017 12:36:11 | BKHOE        | P          | DON        | 248.20     |
| 17-Apr-2017 13:32:0                          | 3,840   | 0       | 285445     | 24-063-003  | Repair Transceiver - GPS Tracker       | 20-Apr-2017 12:57:55 | BKHOE        | I          | DON        | 9.92       |
| 17-Apr-2017 13:32:0                          | 3,840   | 0       | 285445     | 24-360-006  | Repair Lift Arm Assembly               | 21-Apr-2017 12:00:20 | BBKHOE       | B          | DON        | 32.72      |
| 20-Jun-2016 08:18:31                         | 3,054   | 0       | 248803     | 24-360-003  | Repair Drive Train                     | 20-Jun-2016 08:31:44 | BSMEQP       | B          | DON        | 6,247.02   |
| 13-Jan-2014 06:50:46                         | 1,294   | 0       | 142622     | 02-360      | Clean Loader / Skid-Steer              | 22-Jan-2014 15:59:14 | BWASH        | J          | DON        | 137.65     |
| 13-Jan-2014 06:50:46                         | 1,294   | 0       | 142622     | 03-063-003  | Replace Transceiver - GPS Tracker      | 24-Feb-2014 10:52:59 | BSMEQP       | J          | DON        | 284.87     |
| 13-Jan-2014 06:50:46                         | 1,294   | 0       | 142622     | 03-360-004  | Replace Final Drive                    | 24-Feb-2014 10:53:21 | BSMEQP       | I          | DON        | 563.32     |
| 13-Jan-2014 06:50:46                         | 1,294   | 0       | 142622     | 06-030      | Inspect Electrical Group               | 24-Feb-2014 10:53:06 | BSMEQP       | I          | DON        | 38.66      |
| 13-Jan-2014 06:50:46                         | 1,294   | 0       | 142622     | 11-360-011  | Rebuild Quick-Attach Coupling Assembly | 24-Feb-2014 10:53:13 | BSMEQP       | I          | DON        | 621.80     |
| 13-Jan-2014 06:50:46                         | 1,294   | 0       | 142622     | 38-040      | Service Engine / Motor Systems Group   | 24-Feb-2014 10:52:52 | BSMEQP       | J          | DON        | 662.46     |
| 10-Jun-2014 07:43:25                         | 1,507   | 0       | 161013     | 24-360-004  | Repair Final Drive                     | 28-Jun-2014 07:48:54 | BSMEQP       | O          | DON        | 1,598.54   |
| 01-Feb-2016 07:01:18                         | 3,054   | 0       | 231574     | 03-002-061  | Replace Seat Cushion                   | 22-Apr-2016 08:53:10 | BSMEQP       | I          | DON        | 56.72      |
| 01-Feb-2016 07:01:18                         | 3,054   | 0       | 231574     | 03-065-004  | Replace Cylinder                       | 24-Feb-2016 11:21:23 | BSMEQP       | I          | DON        | 2,329.99   |
| 01-Feb-2016 07:01:18                         | 3,054   | 0       | 231574     | 03-065-007  | Replace Hoses & Fittings               | 22-Apr-2016 08:53:25 | BSMEQP       | I          | DON        | 462.85     |
| 01-Feb-2016 07:01:18                         | 3,054   | 0       | 231574     | 03-065-028  | Replace Control Cable                  | 22-Apr-2016 08:52:57 | BSMEQP       | I          | DON        | 349.06     |
| 01-Feb-2016 07:01:18                         | 3,054   | 0       | 231574     | 03-065-031  | Replace Seal / Gasket - Pump           | 22-Apr-2016 08:53:04 | BSMEQP       | I          | DON        | 297.62     |
| 01-Feb-2016 07:01:18                         | 3,054   | 0       | 231574     | 03-360-011  | Replace Quick-Attach Coupling Assembly | 22-Apr-2016 08:52:49 | BSMEQP       | I          | DON        | 1,668.96   |

# Unit Job History

Michels Corporation  
Report Printed: 08-Apr-2019 04:18:13 By User: RHEINING

| WO Open Date                                 | Meter 1 | Meter 2 | Work Order | Job Code    | Job Description                          | Date Completed       | Job Location | Job Reason | Job Status | Total Cost |
|--|---------|---------|------------|-------------|--|----------------------|--------------|------------|------------|------------|
| <b>Unit No: E1012 - 2011 JOHN DEERE 320D</b> |         |         |            |             |  |                      |              |            |            |            |
| 01-Feb-2016 07:01:13                         | 3,054   | 0       | 231574     | 06-063-003  | Inspect Transceiver - GPS Tracker        | 22-Apr-2016 08:53:18 | BBKHOE       | J          | DON        | 55.00      |
| 01-Feb-2016 07:01:13                         | 3,054   | 0       | 231574     | 38-040      | Service Engine / Motor Systems Group     | 22-Apr-2016 08:52:41 | BBSMEQP      | J          | DON        | 503.51     |
| 28-Feb-2018 13:08:33                         | 4,392   | 0       | 325484     | 06-100-PMA  | Inspect A PMI                            | 07-Mar-2018 11:44:15 | BBKHOE       | P          | DON        | 411.12     |
| 28-Feb-2018 13:08:33                         | 4,392   | 0       | 325484     | 21-360-001  | Fabricate Bucket and Attachments         | 28-Feb-2018 16:14:34 | BBKHOE       | P          | DON        | 326.48     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 03-024-004  | Replace Chain Drive                      | 22-Nov-2017 10:56:07 | BBKHOE       | P          | DON        | 386.28     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 03-032-004  | Replace Battery Cables and Ends          | 17-Nov-2017 08:39:59 | BBKHOE       | I          | DON        | 215.33     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 03-042-003  | Replace Fan                              | 22-Nov-2017 11:42:51 | BBKHOE       | I          | DON        | 312.08     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 03-046-002  | Replace Controls - Electro-Mechanical, E | 22-Nov-2017 14:18:50 | BBKHOE       | I          | DON        | 719.48     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 03-065-022  | Replace Flow Control Valve               | 06-Dec-2017 11:57:19 | BBKHOE       | I          | DON        | 511.41     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 03-360-006  | Replace Lift Arm Assembly                | 28-Nov-2017 15:40:19 | BBKHOE       | I          | DON        | 3,126.56   |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 06-100-PMA  | Inspect A PMI                            | 06-Dec-2017 13:52:50 | BBKHOE       | P          | DON        | 673.48     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 19-037-001  | Wire/Rewire Modules - Multiple Use       | 06-Dec-2017 08:44:17 | BBKHOE       | I          | DON        | 115.48     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 24-027-043  | Repair Seal - Output                     | 04-Dec-2017 09:44:33 | BBKHOE       | I          | DON        | 801.45     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 24-042-008  | Repair Oil Cooler                        | 22-Nov-2017 17:00:03 | BBKHOE       | I          | DON        | 288.79     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 24-360-011  | Repair Quick-Attach Coupling Assembly    | 28-Nov-2017 08:01:54 | BBKHOE       | I          | DON        | 445.31     |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 26-360-006  | Weld Lift Arm Assembly                   | 06-Dec-2017 12:23:49 | BBKHOE       | I          | DON        | 0.18       |
| 16-Nov-2017 11:04:0                          | 4,306   | 0       | 312842     | 38-100-PMA  | Service A PMI                            | 06-Dec-2017 14:32:47 | BBKHOE       | I          | DON        | 698.12     |
| 07-Dec-2016 10:42:0                          | 3,650   | 0       | 268879     | 03-054-002  | Replace Alarm - Reverse Signal           | 09-Jan-2017 05:51:03 | BBKHOE       | I          | DON        | 104.14     |
| 07-Dec-2016 10:42:0                          | 3,650   | 0       | 268879     | 03-360-003  | Replace Drive Train                      | 07-Dec-2016 18:22:54 | BBKHOE       | B          | DON        | 356.65     |
| 07-Dec-2016 10:42:0                          | 3,650   | 0       | 268879     | 38-100-PMA  | Service A PMI                            | 09-Jan-2017 08:02:32 | BBKHOE       | P          | DON        | 170.00     |
| 07-Dec-2016 10:42:0                          | 3,650   | 0       | 268879     | 38-032-008  | Service Relay                            | 07-Jan-2017 08:25:45 | BBKHOE       | B          | DON        | 86.22      |
| 07-Dec-2016 10:42:0                          | 3,650   | 0       | 268879     | 38-063-003  | Service Transceiver - GPS Tracker        | 09-Jan-2017 09:39:07 | BBKHOE       | P          | DON        | 56.38      |
| 14-May-2018 15:36:3                          | 4,392   | 0       | 335695     | 24-051-006  | Repair Transceiver - GPS Tracker         | 09-Jan-2017 09:55:20 | BBSMEQP      | Q          | DON        | 0.00       |
| 14-May-2018 15:36:3                          | 4,392   | 0       | 335695     | 24-065-007  | Repair Safety Devices                    | 14-Nov-2018 08:25:59 | BBKHOE       | B          | DON        | 0.00       |
| 01-Apr-2019 06:18:3                          | 5,051   | 0       | 378981     | OS-063-003  | Repair Hoses & Fittings                  | 15-Jun-2018 17:08:23 | BBKHOE       | O          | DON        | 160.29     |
| 01-Apr-2019 06:18:3                          | 5,051   | 0       | 378981     | 06-100-PMIB | Out-Service Transceiver - GPS Tracker    | 04-Apr-2019 14:55:48 | BBKHOE       | Z          | DON        | 72.09      |
| 01-Apr-2019 06:18:3                          | 5,051   | 0       | 378981     | 02-360      | Inspect B PMI                            | 04-Apr-2019 12:58:02 | BBKHOE       | P          | DON        | 359.68     |
|  |         |         |            |             | Clean Loader / Skid-Steer                | 02-Apr-2019 17:00:02 | BWASH        | Z          | DON        | 184.76     |

Unit No: E1012 Count: 86 \$5,142.77