

# Unit Job History

Michels Corporation  
Report Printed: 10-Apr-2019 04:02:23 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
--------------	---------	---------	------------	----------	-----------------	----------------	--------------	------------	------------	------------

Unit No: A0979 - 2000 INTERNATIO 4900

08-Dec-2016 00:00:00	169,794	0	302505	06-100-PMIA	Inspect A PMI	14-Dec-2016 21:00:00	BYLOFC	P	DON	402.85
08-Dec-2016 00:00:00	169,794	0	302505	24-034	Repair Lighting System	14-Dec-2016 21:00:00	BYLOFC	I	DON	92.97
08-Dec-2016 00:00:00	169,794	0	302505	24-173	Repair Tilt Bodies	14-Dec-2016 21:00:00	BYLOFC	I	DON	61.98
08-Dec-2016 00:00:00	169,794	0	302505	34-022-002	Reseal Shaft - Rear Axle	14-Dec-2016 21:00:00	BYLOFC	I	DON	92.97
08-Dec-2016 00:00:00	169,794	0	302505	34-045-013	Reseal Oil Pan	14-Dec-2016 21:00:00	BYLOFC	I	DON	123.95
01-Jun-2018 13:51:36	169,894	0	338062	03-044-023	Replace Primer Pump (Hand)	11-Jun-2018 11:08:11	WTNSHP	I	DON	187.42
08-Mar-2017 07:00:00	169,796	0	294204	03-058-005	Replace Winch Control / Wiring	08-Mar-2017 07:00:00	BYLOFC	N	DON	2,797.09
27-Nov-2017 08:02:5	169,796	0	313612	38-058-001	Service Winch Assembly	28-Nov-2017 12:10:34	WTNSHP	P	DON	321.38
27-Nov-2017 08:02:5	169,796	0	313612	03-032-001	Replace Battery	01-Dec-2017 13:06:08	WTNSHP	P	DON	322.10
08-Dec-2016 00:00:00	169,794	0	302505	34-044-018	Reseal Fuel Hose / Line	14-Dec-2016 21:00:00	BYLOFC	I	DON	61.98
08-Dec-2016 00:00:00	169,794	0	302505	03-023	Replace Clutch	14-Dec-2016 21:00:00	BYLOFC	N	DON	371.86
07-May-2018 10:49:4	169,894	0	334589	03-032-001	Replace Battery	07-May-2018 12:50:04	WTNSHP	I	DON	296.95
14-Jul-2017 11:32:01	169,796	0	296846	24-002-012	Repair Floor Pan	20-Jul-2017 06:43:45	WTNSHP	P	DON	1,004.19
16-Oct-2018 07:01:56	169,895	0	356674	03-017-001	Replace Tire - Pneumatic	13-Nov-2018 12:00:43	BTRUCK	Z	DON	216.76
02-Oct-2018 09:48:34	169,894	0	354658	35-032	Diagnose Cranking System	02-Oct-2018 12:48:23	WTNSHP	I	DON	523.28
12-Dec-2016 07:00:00	168,429	0	272210	03-045-013	Replace Oil Pan	12-Dec-2016 07:00:00	BYLOFC	F	DON	59.00
16-Oct-2018 07:01:56	169,895	0	356674	03-032-001	Replace Battery	13-Nov-2018 12:37:24	BTRUCK	Z	DON	53.14
28-Feb-2018 07:41:24	169,894	0	325395	06-100-PMIA	Inspect A PMI	01-Mar-2018 07:10:58	WTNSHP	P	DON	223.86
16-Oct-2018 07:01:56	169,895	0	356674	24-024-002	Repair Drive Shaft, Behind Main Transm	26-Nov-2018 05:46:16	BTRUCK	Z	DON	1,369.05
16-Oct-2018 07:01:56	169,895	0	356674	25-058	Remove Winch	12-Nov-2018 13:50:16	BTRUCK	Z	DON	73.35
28-Feb-2018 07:41:24	169,894	0	325395	02-002	Clean Cab & Sheet Metal	01-Mar-2018 07:09:40	WTNSHP	I	DON	53.99
28-Feb-2018 07:41:24	169,894	0	325395	06-100-DOT	Inspect DOT Federal Inspection	28-Feb-2018 15:28:34	WTNSHP	P	DON	75.19
28-Feb-2017 04:55:04	179,896	0	278944	14-063-003	Install Transceiver - GPS Tracker	28-Feb-2017 06:45:52	BTRUCK	Q	DON	276.43
03-May-2017 10:39:3	179,896	0	287502	01-023-001	Adjust Linkage - Mechanical Clutch	04-Jun-2017 18:55:17	WTNSHP	I	DON	40.56
03-May-2017 10:39:3	179,896	0	287502	03-013-016	Replace Air Drier / Purge Valve	17-May-2017 06:52:46	WTNSHP	I	DON	196.49
03-May-2017 10:39:3	179,896	0	287502	03-016-006	Replace Shock Absorber - Rear	18-May-2017 14:17:02	WTNSHP	I	DON	244.84
03-May-2017 10:39:3	179,896	0	287502	03-017-001	Replace Tire - Pneumatic	23-May-2017 13:29:58	WTNSHP	I	DON	3,502.45
03-May-2017 10:39:3	179,896	0	287502	02-002-044	Clean Cab - Complete	04-May-2017 13:09:58	WTNSHP	I	DON	267.77
03-May-2017 10:39:3	179,896	0	287502	03-002-035	Replace Windshield Wiper & Washer	04-Jun-2017 18:55:22	WTNSHP	I	DON	14.34

# Unit Job History

Michels Corporation  
Report Printed: 10-Apr-2019 04:02:23 By User: RHEENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: A0979 - 2000 INTERNATIO 4900										
03-May-2017 10:39:3	179,896	0	287502	03-053-005	Replace Markings - Vehicle - Decals	04-May-2017 13:19:42	WTNSHP	I	DON	7.96
03-May-2017 10:39:3	179,896	0	287502	03-034-010	Replace Socket - Trailer Light Cord	16-May-2017 14:00:47	WTNSHP	I	DON	62.73
03-May-2017 10:39:3	179,896	0	287502	03-042-014	Replace Coolant Overflow Reservoir	18-May-2017 13:07:30	WTNSHP	I	DON	24.27
03-May-2017 10:39:3	179,896	0	287502	03-032-001	Replace Battery	16-May-2017 12:16:12	WTNSHP	I	DON	341.82
03-May-2017 10:39:3	179,896	0	287502	06-100-009	Inspect Safety Check	18-May-2017 15:12:25	WTNSHP	P	DON	155.24
03-May-2017 10:39:3	179,896	0	287502	03-044-013	Replace Cap - Fuel Tank	16-May-2017 10:53:01	WTNSHP	I	DON	0.00
03-May-2017 10:39:3	179,896	0	287502	03-053-004	Replace Safety Equipment	04-May-2017 13:16:18	WTNSHP	I	DON	119.73
04-Apr-2019 08:17:1	169,895	0	379712	25-052-003	Remove Radio Equipment	08-Apr-2019 15:35:03	BSETUP	Z	DON	10.45
04-Apr-2019 08:17:1	169,895	0	379712	25-053-005	Remove Markings - Vehicle - Decals	08-Apr-2019 15:17:28	BSETUP	Z	DON	55.45
03-May-2017 10:39:3	179,896	0	287502	03-053-007	Replace Hardware - Expendable Items	05-May-2017 16:02:38	WTNSHP	I	DON	80.04
03-May-2017 10:39:3	179,896	0	287502	38-058-002	Service Cable	19-May-2017 12:07:54	WTNSHP	P	DON	59.62
03-May-2017 10:39:3	179,896	0	287502	06-100-DOT	Inspect DOT Federal Inspection	17-May-2017 09:31:47	WTNSHP	I	DON	82.13
04-Apr-2019 08:17:1	169,895	0	379712	02-002	Clean Cab & Sheet Metal	08-Apr-2019 17:04:16	BSETUP	Z	DON	97.33
03-May-2017 10:39:3	179,896	0	287502	24-078-009	Repair Mud Flaps and Hanger Brackets	04-May-2017 13:25:18	WTNSHP	I	DON	2.89
04-Apr-2019 08:17:1	169,895	0	379712	25-063-003	Remove Transceiver - GPS Tracker	08-Apr-2019 17:03:51	BSETUP	Z	DON	39.91

Unit No: A0979

Count: 44

14,467.76