

# Unit Job History

Michels Corporation  
Report Printed: 25-Apr-2019 12:42:06 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2194 - 2013 F150 SUPERCREW</b>										
25-Jun-2018 13:09:55	178,641	0	341229	02-002	Clean Cab & Sheet Metal	25-Jun-2018 14:19:43	LAVSHP	I	DON	33.81
25-Jun-2018 13:09:55	178,641	0	341229	06-100-PMA	Inspect A PMI	03-Jul-2018 09:47:56	LAVSHP	P	DON	49.29
14-May-2018 14:38:00	173,100	0	340801	03-034	Replace Lighting System	14-May-2018 14:39:00	BVLOFC	O	DON	17.39
14-Jun-2018 13:18:00	246,755	0	366891	06-100-PMA	Inspect A PMI	14-Jun-2018 13:26:00	BVLOFC	P	DON	44.52
14-Jun-2018 13:18:00	246,755	0	366891	09-015	Align Steering	14-Jun-2018 13:26:00	BVLOFC	I	DON	34.17
14-Jun-2018 13:18:00	246,755	0	366891	31-017	Rotate Tires, Tubes, Liners & Valves	14-Jun-2018 13:27:00	BVLOFC	P	DON	21.17
14-Jun-2018 13:18:00	246,755	0	366891	35-015	Diagnose Steering	14-Jun-2018 13:27:00	BVLOFC	O	DON	127.35
06-Sep-2016 15:54:11	125,170	0	258387	03-044-003	Replace Fuel Pump	07-Sep-2016 06:52:37	LAVSHP	B	DON	387.16
03-Nov-2017 12:13:5	151,792	0	311336	03-013-001	Replace Front Brakes & Drums	03-Nov-2017 18:26:06	LAVSHP	B	DON	312.99
03-Nov-2017 12:13:5	151,792	0	311336	03-013-037	Replace Caliper - Front	06-Nov-2017 17:05:27	LAVSHP	B	DON	185.38
13-Dec-2018 12:44:00	246,755	0	369167	06-016-020	Inspect Ball Joint - Upper Control Arm	13-Dec-2018 12:45:00	BVLOFC	O	DON	150.88
13-Dec-2018 12:44:00	246,755	0	369167	06-100-PMA	Inspect A PMI	13-Dec-2018 12:47:00	BVLOFC	P	DON	76.36
29-Jun-2016 11:16:52	117,518	0	250097	03-033-003	Replace Spark Plugs	29-Jun-2016 13:11:13	LAVSHP	P	DON	68.52
15-Mar-2013 12:33:5	60	0	111178	01-042	Adjust Cooling System	18-Mar-2013 05:59:06	BTRUCK	I	DON	22.11
15-Mar-2013 12:33:5	60	0	111178	06-100-009	Inspect Safety Check	18-Mar-2013 06:40:05	BTRUCK	P	DON	22.39
15-Mar-2013 12:33:5	60	0	111178	14-053-005	Install Markings - Vehicle - Decals	15-Mar-2013 15:43:10	BBODY	J	DON	14.18
15-Mar-2013 12:33:5	60	0	111178	14-053-014	Install Floor Mats	15-Mar-2013 15:48:15	BBODY	C	DON	78.70
15-Mar-2013 12:33:5	60	0	111178	14-063-003	Install Transceiver - GPS Tracker	16-Mar-2013 09:44:05	BBODY	C	DON	344.90
15-Mar-2013 12:33:5	60	0	111178	14-071-011	Install Scaff Liner / Bed Mat	15-Mar-2013 15:13:17	BBODY	C	DON	83.20
15-Mar-2013 12:33:5	60	0	111178	14-078-009	Install Mud Flaps and Hanger Brackets	15-Mar-2013 14:59:33	BBODY	C	DON	97.26
15-Mar-2013 12:33:5	60	0	111178	14-078-014	Install Tarpanlin	15-Mar-2013 16:42:30	BBODY	C	DON	438.31
06-Nov-2018 10:45:1	187,200	0	359672	06-100-009	Inspect Safety Check	06-Nov-2018 12:28:57	BTRUCK	P	DON	55.62
05-Nov-2018 06:40:3	182,639	0	359407	03-002-024	Replace Glass / Windshield	05-Nov-2018 06:42:58	BVLOFC	I	DON	337.21
17-Oct-2016 09:32:48	129,118	0	263213	03-042	Replace Cooling System	17-Oct-2016 11:11:24	LAVSHP	B	DON	105.29
26-Mar-2013 15:29:4	60	0	117677	38-MSC	Service Miscellaneous	26-Mar-2013 15:30:09	BVLOFC	F	DON	328.26
18-Jul-2017 08:18:56	144,205	0	297155	03-017-001	Replace Tire - Pneumatic	20-Jul-2017 11:21:59	BTIRE	F	DON	944.12
18-Jul-2017 08:18:56	144,205	0	297155	06-100-PMA	Inspect A PMI	18-Jul-2017 09:28:38	LAVSHP	P	DON	60.71
18-Jul-2017 08:18:56	144,205	0	297155	31-017-001	Rotate Tire - Pneumatic	18-Jul-2017 09:47:49	LAVSHP	P	DON	9.44
12-Nov-2018 16:11:5	187,200	0	360409	02-002	Clean Cab & Sheet Metal	15-Nov-2018 17:02:09	BSETUP	Z	DON	415.13

# Unit Job History

Michels Corporation  
 Report Printed: 25-Apr-2019 12:42:06 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: B2194 - 2013 F150 SUPERCREW</b>										
12-Nov-2018 16:11:5	187,200	0	360409	25-063-003	Remove Transceiver - GPS Tracker	15-Nov-2018 13:56:38	BSETUP	Z	DON	19.35
22-May-2015 11:45:3	73,057	0	205391	03-017-001	Replace Tire - Pneumatic	22-May-2015 11:45:51	BTIRE	N	DON	849.08
03-Oct-2017 13:53:02	147,375	0	307386	14-034-006	Install Warning Lamps - Special Applicat	03-Oct-2017 14:21:17	LAVSHP	O	DON	292.53
12-Apr-2016 10:03:1	109,476	0	240875	03-013-002	Replace Rear Brakes & Drums	12-Apr-2016 11:08:31	LAVSHP	P	DON	306.93
09-Sep-2016 11:39:0	125,229	0	258860	03-037-021	Replace Circuite Breaker/Fuse - Multiple	09-Sep-2016 12:44:21	LAVSHP	I	DON	45.28
19-Mar-2018 12:45:5	166,372	0	327819	24-002-024	Repair Glass / Windshield	21-Mar-2018 11:11:33	LAVSHP	B	DON	63.85
29-Aug-2018 06:00:0	182,639	0	350393	03-002-018	Replace Cab Or Front Door Mechanism	31-Aug-2018 16:00:00	NBSHP	O	DON	307.04
29-Aug-2018 06:00:0	182,639	0	350393	03-013-001	Replace Front Brakes & Drums	31-Aug-2018 16:00:00	NBSHP	O	DON	346.08
24-Jan-2017 13:09:29	136,560	0	274639	03-042-004	Replace Water Pump	24-Jan-2017 17:49:55	LAVSHP	I	DON	162.32
24-Jan-2017 13:09:29	136,560	0	274639	03-045-026	Replace Tensioner - Engine Belts	24-Jan-2017 18:08:52	LAVSHP	I	DON	30.73
24-Jan-2017 13:09:29	136,560	0	274639	06-045-026	Inspect Tensioner - Engine Belts	24-Jan-2017 13:42:26	LAVSHP	O	DON	54.90
26-May-2016 09:50:4	114,132	0	245967	03-032-001	Replace Battery	26-May-2016 10:25:22	LAVSHP	I	DON	139.45
31-Mar-2015 06:00:0	73,057	0	197295	03-013	Replace Brakes	31-Mar-2015 17:00:00	LAKEVL	S	DON	61.86
10-Jul-2013 00:00:00	60	0	124152	03-063-003	Replace Transceiver - GPS Tracker	10-Jul-2013 00:00:00	BTRUCK	C	DON	221.42
12-Jul-2018 10:05:03	178,641	0	343508	02-002	Clean Cab & Sheet Metal	12-Jul-2018 16:01:25	BSETUP	N	DON	159.66
31-May-2016 08:37:3	114,333	0	246290	03-031-001	Replace Generator/Alternator	31-May-2016 14:01:50	LAVSHP	I	DON	377.79
31-May-2016 08:37:3	114,333	0	246290	35-003-001	Diagnose Gauges & Warning Devices	31-May-2016 09:02:50	LAVSHP	O	DON	12.49

Unit No: B2194

Count: 46

8,316.58