

Unit Job History

Michels Corporation
Report Printed: 27-Feb-2019 07:46:59 By User: KM/ARTIN

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Job Status	Total Cost
Unit No: B2577 - 2014 F150 SUPERCREW											
26-Mar-2014	1	28	0	151795	06-100-009	Inspect Safety Check	03-Apr-2014 06:52:33	BTRUCK	P	DON	37.53
26-Mar-2014	1	28	0	151795	14-002-059	Install Protector - Tail Gate	02-Apr-2014 15:55:26	BDETL	C	DON	129.03
26-Mar-2014	1	28	0	151795	14-034-006	Install Warning Lamps - Special Application	02-Apr-2014 12:07:11	BDETL	C	DON	326.51
26-Mar-2014	1	28	0	151795	14-052-001	Install Cigar Lighter	02-Apr-2014 10:19:42	BDETL	C	DON	34.02
26-Mar-2014	1	28	0	151795	14-052-003	Install Radio Equipment	02-Apr-2014 08:16:37	BDETL	C	DON	912.56
26-Mar-2014	1	28	0	151795	14-052-011	Install Auxiliary Power	01-Apr-2014 16:51:44	BDETL	C	DON	183.95
26-Mar-2014	1	28	0	151795	14-052-015	Install Power Inverter/Converter	03-Apr-2014 06:12:17	BDETL	C	DON	416.85
26-Mar-2014	1	28	0	151795	14-053-005	Install Markings - Vehicle - Decals	02-Apr-2014 06:44:42	BDETL	C	DON	8.31
26-Mar-2014	1	28	0	151795	14-071-011	Install Scuff Liner / Bed Mat	02-Apr-2014 09:30:32	BDETL	C	DON	108.80
26-Mar-2014	1	28	0	151795	14-078-009	Install Mud Flaps and Hanger Brackets	03-Apr-2014 06:12:09	BDETL	C	DON	75.53
26-Mar-2014	1	28	0	151795	14-078-014	Install Tarpsaulin	03-Apr-2014 06:12:01	BDETL	C	DON	475.45
26-Mar-2014	1	28	0	151795	14-510-002	Install Tool Box	02-Apr-2014 11:21:43	BDETL	C	DON	352.93
09-Sep-2015	1	64.615	0	226064	06-100-PMA	Inspect A PMI	09-Sep-2015 11:16:31	BVLOFC	P	DON	132.79
16-Nov-2015	0	64.615	0	222056	06-100-PMA	Inspect A PMI	16-Nov-2015 08:50:17	BVLOFC	P	DON	69.60
18-Mar-2016	1	81.232	0	238143	03-013-001	Replace Front Brakes & Drums	21-Mar-2016 07:09:28	BVLOFC	I	DON	285.41
18-Mar-2016	1	81.232	0	238143	03-041-007	Replace Filter - Outer	21-Mar-2016 07:06:07	BVLOFC	P	DON	33.50
18-Mar-2016	1	81.232	0	238143	06-100-PMA	Inspect A PMI	21-Mar-2016 07:20:33	BVLOFC	P	DON	57.24
18-Mar-2016	1	81.232	0	238143	38-022-003	Service Differential Carrier	21-Mar-2016 07:08:39	BVLOFC	P	DON	159.73
11-Apr-2016	1	84.300	0	240798	24-042	Repair Cooling System	26-Apr-2016 14:39:29	BVLOFC	O	DON	343.90
16-May-2016	0	88.289	0	251659	06-100-PMA	Inspect A PMI	16-May-2016 07:00:45	BVLOFC	P	DON	40.80
16-May-2016	0	88.289	0	251659	31-017-001	Rotate Tire - Pneumatic	16-May-2016 07:03:01	BVLOFC	P	DON	22.48
08-Jul-2016	07	95.625	0	256961	06-100-PMA	Inspect A PMI	08-Jul-2016 11:01:49	BVLOFC	P	CAN	0.00
08-Jul-2016	10	95.625	0	257286	06-100-PMA	Inspect A PMI	15-Sep-2016 15:42:32	BVLOFC	P	DON	79.28
15-Sep-2016	1	105.371	0	266330	06-100-PMA	Inspect A PMI	27-Sep-2016 08:57:20	BVLOFC	P	DON	69.04
27-Sep-2016	0	105.371	0	260839	06-100-PMA	Inspect A PMI	27-Sep-2016 08:58:30	BVLOFC	P	DON	20.95
27-Sep-2016	0	105.371	0	260839	31-017-001	Rotate Tire - Pneumatic	27-Sep-2016 08:57:20	BVLOFC	P	DON	39.61
08-Nov-2016	0	114.733	0	265873	03-032-001	Replace Battery	10-Nov-2016 15:29:33	BVLOFC	I	DON	134.00
08-Nov-2016	0	114.733	0	265873	03-041-007	Replace Filter - Outer	10-Nov-2016 15:28:10	BVLOFC	P	DON	22.29
08-Nov-2016	0	114.733	0	265873	06-100-PMA	Inspect A PMI	10-Nov-2016 15:32:55	BTRUCK	P	DON	51.40

Unit Job History

Michels Corporation
Report Printed: 27-Feb-2019 07:46:59 By User: KMARTIN

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2577 - 2014 F150 SUPERCREW										
08-Nov-2016	0	114,733	265873	38-027	Service Transmission - Main, Automatic	10-Nov-2016 15:30:23	BVLOFC	P	DON	189.85
08-Nov-2016	0	114,733	265873	38-042	Service Cooling System	10-Nov-2016 15:31:33	BVLOFC	P	DON	179.18
21-Jan-2017	0	124,796	289124	06-100-PMA	Inspect A PMI	21-Jan-2017 09:18:55	BVLOFC	P	DON	44.80
10-Mar-2017	1	105,371	280585	03-017-001	Replace Tire - Pneumatic	10-Mar-2017 14:57:46	BTRIRE	F	DON	1,019.55
14-Mar-2017	0	136,771	284693	06-100-PMA	Inspect A PMI	14-Mar-2017 08:27:52	BVLOFC	P	DON	62.54
14-Jun-2017	1	149,243	299077	06-100-PMA	Inspect A PMI	14-Jun-2017 11:43:21	BTRUCK	P	DON	61.30
16-Aug-2017	1	157,145	301323	06-100-PMA	Inspect A PMI	16-Aug-2017 11:16:39	BVLOFC	P	DON	73.11
14-Nov-2017	1	159,694	312480	24-032	Repair Cranking System	22-Jan-2018 13:32:16	BVLOFC	O	DON	483.99
05-Sep-2018	1	179,150	350947	06-100-PMA	Inspect A PMI	05-Sep-2018 13:53:16	BVLOFC	P	DON	64.36
10-Sep-2018	0	179,486	351356	03-013	Replace Brakes	10-Sep-2018 06:04:56	BVLOFC	O	DON	679.18
25-Oct-2018	1	184,086	358216	03-002-024	Replace Glass / Windshield	25-Oct-2018 13:21:53	BVLOFC	O	DON	379.88
25-Oct-2018	1	184,086	358216	06-100-PMA	Inspect A PMI	25-Oct-2018 13:21:53	BVLOFC	P	DON	64.37
11-Dec-2018	1	189,329	363958	03-032-001	Replace Battery	11-Dec-2018 14:33:14	BVLOFC	O	DON	170.12
11-Dec-2018	1	189,329	363958	06-100-PMA	Inspect A PMI	11-Dec-2018 14:33:14	BVLOFC	P	DON	64.37
12-Dec-2018	1	189,383	364102	03-032-001	Replace Battery	12-Dec-2018 11:41:10	BVLOFC	I	DON	170.12
12-Dec-2018	1	189,383	364102	06-100-PMB	Inspect B PMI	12-Dec-2018 11:41:10	BVLOFC	P	DON	64.37
24-Jan-2019	0	197,707	373094	06-100-PMA	Inspect A PMI	24-Jan-2019 09:59:00	BVLOFC	P	DON	72.71
25-Feb-2019	1	198,868	373995	06-100-009	Inspect Safety Check	27-Feb-2019 07:22:04	BTRUCK	P	DON	107.78

Unit No: B2577

Count: 47

8,575.06