

Unit Job History

Michels Corporation
Report Printed: 03-Apr-2019 11:34:19 By User: RHEVENING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
20-May-2014 07:15:1	792	0	158466	03-020	Replace Drivetrain Group	18-Jun-2014 08:57:41	BSMEQP	B	DON	2,435.64
30-Sep-2014 15:08:1	1,005	0	174113	19-360-008	Wire/Rewire Operator Controls	30-Sep-2014 15:16:56	BSMEQP	B	DON	1,001.04
04-Feb-2015 06:31:4	1,350	0	190028	02-360	Clean Loader / Skid-Steer	05-Feb-2015 08:35:37	BWASH	J	DON	126.98
04-Feb-2015 06:31:4	1,350	0	190028	03-065-004	Replace Cylinder	18-Feb-2015 11:37:21	BSMEQP	I	DON	319.69
04-Feb-2015 06:31:4	1,350	0	190028	03-360-004	Replace Final Drive	18-Feb-2015 11:37:12	BSMEQP	I	DON	1,056.45
04-Feb-2015 06:31:4	1,350	0	190028	11-360-011	Rebuild Quick-Attach Coupling Assembl	18-Feb-2015 11:36:40	BSMEQP	I	DON	1,576.67
04-Feb-2015 06:31:4	1,350	0	190028	38-040	Service Engine / Motor Systems Group	18-Feb-2015 11:36:31	BSMEQP	J	DON	520.95
22-Sep-2015 08:13:1	1,862	0	217796	24-360-003	Repair Drive Train	22-Sep-2015 08:17:40	BVLOFC	O	DON	1,169.71
08-Jul-2015 12:55:38	1,711	0	206987	24-020	Repair Drivetrain Group	12-Aug-2015 13:58:19	BSMEQP	B	DON	4,931.53
17-Apr-2017 11:50:0	2,693	0	285422	03-065-004	Replace Cylinder	16-May-2017 17:32:18	BBKHOE	B	DON	1,856.00
17-Apr-2017 11:50:0	2,693	0	285422	03-065-008	Replace Line / Tubing Assembly	02-Jun-2017 09:01:16	BBKHOE	B	DON	92.01
17-Jul-2017 16:06:18	3,118	0	297086	03-065-004	Replace Cylinder	18-Jul-2017 08:45:01	BBKHOE	F	DON	710.03
03-Nov-2012 08:39:1	1	0	100075	14-063-003	Install Transceiver - GPS Tracker	05-Nov-2012 09:43:45	BSMEQP	J	DON	336.98
07-Nov-2016 14:19:0	2,556	0	265799	03-044-007	Replace Throttle Controls	08-Nov-2016 12:00:48	BBKHOE	B	DON	458.31
07-Nov-2016 14:19:0	2,556	0	265799	24-013-030	Repair Switch - Parking Brake	23-Nov-2016 15:35:40	BBKHOE	B	DON	360.06
21-Dec-2017 06:34:5	3,153	0	317028	03-002-006	Replace Roof Panel & Reinforcements	10-Jan-2018 09:13:46	BBKHOE	I	DON	21.81
21-Dec-2017 06:34:5	3,153	0	317028	03-002-022	Replace Rear Door Mechanism	08-Jan-2018 09:30:10	BBKHOE	I	DON	39.26
21-Dec-2017 06:34:5	3,153	0	317028	03-022-001	Replace Axle Housing, Rear	09-Jan-2018 16:40:26	BBKHOE	I	DON	668.39
21-Dec-2017 06:34:5	3,153	0	317028	03-031-001	Replace Generator/Alternator	10-Jan-2018 08:37:17	BBKHOE	I	DON	23.38
21-Dec-2017 06:34:5	3,153	0	317028	03-032-001	Replace Battery	08-Jan-2018 08:24:29	BBKHOE	I	DON	189.71
21-Dec-2017 06:34:5	3,153	0	317028	03-042-016	Replace Fan Clutch	10-Jan-2018 07:56:45	BBKHOE	I	DON	852.33
21-Dec-2017 06:34:5	3,153	0	317028	03-065-007	Replace Hoses & Fittings	10-Jan-2018 10:56:38	BBKHOE	I	DON	55.61
21-Dec-2017 06:34:5	3,153	0	317028	06-100-PM A	Inspect A PMI	10-Jan-2018 10:57:02	BBKHOE	P	DON	1,050.48
21-Dec-2017 06:34:5	3,153	0	317028	10-360-006	Rebush Lift Arm Assembly	08-Jan-2018 11:48:47	BBKHOE	I	DON	229.78
21-Dec-2017 06:34:5	3,153	0	317028	10-360-011	Rebush Quick-Attach Coupling Assembly	09-Jan-2018 15:46:27	BBKHOE	I	DON	502.48
14-Mar-2016 16:33:1	2,180	0	237390	01-065-015	Adjust Pump - Variable Displacement Ty	22-Apr-2016 08:42:35	BSMEQP	I	DON	141.35
14-Mar-2016 16:33:1	2,180	0	237390	03-002-061	Replace Seat Cushion	22-Apr-2016 08:42:55	BSMEQP	I	DON	321.34
14-Mar-2016 16:33:1	2,180	0	237390	03-042-004	Replace Water Pump	22-Apr-2016 08:42:48	BSMEQP	I	DON	205.97
14-Mar-2016 16:33:1	2,180	0	237390	03-065-004	Replace Cylinder	22-Apr-2016 08:42:29	BSMEQP	I	DON	3,140.69

Unit Job History

Mitchels Corporation
Report Printed: 03-Apr-2019 11:34:19 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E1065 - 2012 JOHN DEERE 320D										
14-Mar-2016 16:33:1	2,180	0	237390	03-065-028	Replace Control Cable	22-Apr-2016 08:42:41	BSMEQP	I	DON	421.27
14-Mar-2016 16:33:1	2,180	0	237390	03-065-031	Replace Seal / Gasket - Pump	22-Apr-2016 08:43:02	BSMEQP	I	DON	142.46
14-Mar-2016 16:33:1	2,180	0	237390	06-030	Inspect Electrical Group	22-Apr-2016 08:43:08	BSMEQP	I	DON	29.32
14-Mar-2016 16:33:1	2,180	0	237390	06-360-011	Inspect Quick-Attach Coupling Assembly	22-Apr-2016 08:42:17	BSMEQP	J	DON	334.82
14-Mar-2016 16:33:1	2,180	0	237390	38-040	Service Engine / Motor Systems Group	22-Apr-2016 08:42:10	BSMEQP	J	DON	1,871.17
25-Apr-2018 14:10:5	3,300	0	332965	03-013-003	Replace Brake Chamber - Parking	25-Apr-2018 16:18:21	BBKH0E	I	DON	208.91
25-Apr-2018 14:10:5	3,300	0	332965	03-031-006	Replace Belt - Alternator	26-Apr-2018 17:00:37	BBKH0E	I	DON	366.99
25-Apr-2018 14:10:5	3,300	0	332965	21-360-001	Fabricate Bucket and Attachments	27-Apr-2018 09:51:32	BBKH0E	P	DON	123.57
25-Apr-2018 14:10:5	3,300	0	332965	34-022-007	Reseal Axle Assembly - Driven, Rear	26-Apr-2018 16:04:47	BBKH0E	P	DON	224.85
25-Apr-2018 14:10:5	3,300	0	332965	38-100-PMA	Service A PMI	27-Apr-2018 08:54:40	BBKH0E	P	DON	254.12
24-Jun-2014 10:25:28	792	0	162824	24-360-011	Repair Quick-Attach Coupling Assembly	19-Sep-2014 06:58:59	BSMEQP	B	DON	705.31
25-Oct-2017 11:39:44	3,145	0	310167	03-360-008	Replace Operator Controls	02-Nov-2017 09:46:44	BBKH0E	B	DON	630.13
25-Oct-2017 11:39:44	3,145	0	310167	06-065-001	Inspect Hydraulic Systems	02-Nov-2017 09:47:20	BBKH0E	B	DON	1,276.40
25-Oct-2017 11:39:44	3,145	0	310167	38-100-PMA	Service A PMI	25-Oct-2017 17:00:21	BBKH0E	P	DON	240.11
09-May-2016 08:23:2	2,241	0	243836	24-360-003	Repair Drive Train	31-May-2016 14:18:46	BSMEQP	B	DON	3,043.87
02-Dec-2016 09:00:0	2,640	0	268440	03-002-015	Replace Quarter & Deck Panels - Rear	15-Dec-2016 06:27:09	BBKH0E	I	DON	482.76
02-Dec-2016 09:00:0	2,640	0	268440	03-360-008	Replace Operator Controls	15-Dec-2016 06:27:17	BBKH0E	I	DON	419.96
02-Dec-2016 09:00:0	2,640	0	268440	06-100-PM/A	Inspect A PMI	13-Dec-2016 09:49:44	BSMEQP	P	DON	309.78
02-Dec-2016 09:00:0	2,640	0	268440	06-100-PM/B	Inspect B PMI	15-Dec-2016 09:00:29	BSMEQP	P	DON	92.12
02-Dec-2016 09:00:0	2,640	0	268440	14-065-004	Install Cylinder	15-Dec-2016 12:01:21	BBKH0E	P	DON	573.27
02-Dec-2016 09:00:0	2,640	0	268440	24-013	Repair Brakes	13-Dec-2016 06:46:19	BBKH0E	B	DON	3,294.72
02-Dec-2016 09:00:0	2,640	0	268440	25-065-004	Remove Cylinder	09-Dec-2016 08:41:53	BBKH0E	P	DON	101.18
24-Apr-2014 06:00:0	725	0	162034	24-360-008	Repair Operator Controls	30-Apr-2014 17:00:00	BVLOFC	F	DON	622.06
29-Aug-2016 13:14:3	2,241	0	257529	03-032-001	Replace Battery	21-Sep-2016 10:25:09	BSMEQP	I	DON	0.00
29-Aug-2016 13:14:3	2,241	0	257529	24-360-003	Repair Drive Train	16-Sep-2016 06:50:14	BSMEQP	B	DON	1,368.45
15-Aug-2017 17:17:3	3,248	0	301220	03-002-014	Replace Panel Deadeners	28-Sep-2017 07:16:10	BBKH0E	I	DON	345.77
15-Aug-2017 17:17:3	3,248	0	301220	03-360-004	Replace Final Drive	28-Sep-2017 07:16:16	BBKH0E	B	DON	223.66
15-Aug-2017 17:17:3	3,248	0	301220	24-033	Repair Ignition System	20-Sep-2017 11:49:03	BBKH0E	O	DON	78.56
15-Aug-2017 17:17:3	3,248	0	301220	35-037-011	Diagnose Relay - Multiple Use	28-Sep-2017 07:05:22	BBKH0E	B	DON	223.32

Unit Job History

Michels Corporation
Report Printed: 03-Apr-2019 11:34:19 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: E1065 - 2012 JOHN DEERE 320D										
21-Jul-2017 12:30:45	3,118	0	297773	03-017-005	Replace Tire - Solid	02-Aug-2017 10:31:36	BBKHOE	N	DON	1,950.02
21-Jul-2017 12:30:45	3,118	0	297773	03-065-005	Replace Drive - Motor / Pump	02-Aug-2017 08:06:50	BBKHOE	B	DON	6,482.12
21-Jul-2017 12:30:45	3,118	0	297773	03-360-004	Replace Final Drive	28-Jul-2017 09:31:44	BBKHOE	B	DON	792.91
21-Jul-2017 12:30:45	3,118	0	297773	06-065-005	Inspect Drive - Motor / Pump	02-Aug-2017 10:32:04	BBKHOE	I	DON	287.98
21-Jul-2017 12:30:45	3,118	0	297773	24-360-011	Repair Quick-Attach Coupling Assembly	27-Jul-2017 10:14:27	BBKHOE	B	DON	65.06
21-Jul-2017 12:30:45	3,118	0	297773	38-100-PMA	Service A PMI	02-Aug-2017 10:32:14	BBKHOE	P	DON	133.45
30-Jan-2014 11:21:34	636	0	144912	02-360	Clean Loader / Skid-Steer	06-Feb-2014 08:02:09	BWASH	J	DON	165.35
30-Jan-2014 11:21:34	636	0	144912	03-030	Replace Electrical Group	24-Feb-2014 11:01:23	BSMEQP	I	DON	105.87
30-Jan-2014 11:21:34	636	0	144912	03-063-003	Replace Transceiver - GPS Tracker	24-Feb-2014 11:01:31	BSMEQP	J	DON	291.45
30-Jan-2014 11:21:34	636	0	144912	11-360-011	Rebuild Quick-Attach Coupling Assembly	24-Feb-2014 11:01:39	BSMEQP	I	DON	580.66
25-Apr-2018 09:23:33	3,153	0	332899	02-360	Service Engine / Motor Systems Group	24-Feb-2014 11:01:15	BSMEQP	J	DON	444.50
26-Oct-2012 06:32:02	0	0	99532	12-360-001	Clean Loader / Skid-Steer	25-Apr-2018 15:36:32	BWASH	J	DON	189.82
26-Oct-2012 06:32:02	0	0	99532	21-360-001	Refinish Bucket and Attachments	05-Nov-2012 10:39:13	BBODY	H	DON	94.27
26-Oct-2012 06:32:02	0	0	99532	22-360-001	Fabricate Bucket and Attachments	05-Nov-2012 16:27:52	BWELD	C	DON	1,210.97
04-Feb-2019 14:20:11	3,950	0	371053	02-360	Design Bucket and Attachments	26-Oct-2012 09:00:00	BDRAW	D	DON	64.84
04-Feb-2019 14:20:11	3,950	0	371053	03-032-002	Clean Loader / Skid-Steer	06-Feb-2019 17:00:25	BWASH	N	DON	418.40
04-Feb-2019 14:20:11	3,950	0	371053	06-100-PMA	Replace Starter	15-Feb-2019 12:51:43	BBKHOE	I	DON	251.71
04-Feb-2019 14:20:11	3,950	0	371053	24-013	Inspect A PMI	11-Feb-2019 07:00:16	BBKHOE	P	DON	920.07
04-Feb-2019 14:20:11	3,950	0	371053	06-100-PMB	Repair Brakes	15-Feb-2019 12:51:48	BBKHOE	I	DON	330.17
04-Feb-2019 14:20:11	3,950	0	371053	OS-063-003	Inspect B PMI	13-Feb-2019 11:26:26	BSMEQP	P	DON	499.60
04-Feb-2019 14:20:11	3,950	0	371053	24-065-031	Out-Service Transceiver - GPS Tracker	15-Feb-2019 13:36:20	BBKHOE	Z	DON	10.54
04-Feb-2019 14:20:11	3,950	0	371053	24-065-031	Repair Seal / Gasket - Pump	29-Mar-2019 12:00:25	BBKHOE	I	DON	117.68

Unit No: E1065

Count: 80

57,810.98