

Unit Job History

Michels Corporation
Report Printed: 17-Nov-2020 11:57:22 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: H0412 - 2003 CASE 960										
12-Sep-2018 11:57:31	2,006	0	351791	03-032-001	Replace Battery	19-Sep-2018 13:24:58	BSMEQP	Z	DON	183.56
27-Oct-2014 06:00:00	1,910	0	184335	24-305	Repair Trencher	27-Oct-2014 17:00:00	BYLOFC	F	DON	6,150.07
29-Nov-2017 10:29:4	2,006	0	314048	03-032-001	Replace Battery	29-Nov-2017 13:15:01	ROGSHHP	N	DON	267.93
29-Nov-2017 10:29:4	2,006	0	314048	03-065-007	Replace Hoses & Fittings	29-Nov-2017 12:56:40	ROGSHHP	B	DON	87.26
07-Apr-2016 15:23:2	1,970	0	240485	04-325	Rig / Unrig Cable Plow	25-Apr-2016 09:21:47	LAVSHP	J	DON	21.58
25-Jul-2014 09:35:32	1,862	0	167004	24-017-001	Repair Tire - Pneumatic	25-Jul-2014 09:35:52	BTIRE	E	DON	44.04
07-Apr-2016 15:23:2	1,970	0	240485	24-065-011	Repair Motor - Piston Type	25-Apr-2016 13:14:36	LAVSHP	B	DON	799.46
05-Dec-2019 10:56:4	2,006	0	415408	24-325	Repair Cable Plow	10-Dec-2019 08:49:11	BSMEQP	Z	DON	29.62
27-Oct-2014 06:00:00	1,910	0	184335	11-305	Rebuild Trencher		BYLOFC	F	CAN	0.00
12-Sep-2018 11:57:31	2,006	0	351791	15-305	Paint Prep Trencher	19-Sep-2018 13:24:47	BBODY	Z	DON	1,486.53
12-Sep-2018 11:57:31	2,006	0	351791	12-305	Refinish Trencher	19-Sep-2018 13:24:50	BBODY	Z	DON	801.40
08-Oct-2015 07:19:27	1,953	0	221425	03-065-007	Replace Hoses & Fittings	08-Oct-2015 07:20:43	BYLOFC	O	DON	299.60
05-Dec-2019 10:56:4	2,006	0	415408	03-044-002	Replace Filters	05-Dec-2019 13:32:42	BSMEQP	Z	DON	62.86
05-Mar-2014 06:00:00	1,862	0	151424	06-100-PMB	Inspect B PMI	05-Mar-2014 17:00:00	LAKEVL	P	DON	21.01
05-Mar-2014 06:00:00	1,862	0	151424	07-100-300	Lubricate Off Road Equip / Field Service	05-Mar-2014 17:00:00	LAKEVL	P	DON	21.01
18-Nov-2014 10:42:3	1,897	0	181263	24-017-001	Repair Tire - Pneumatic	18-Nov-2014 10:42:50	BTIRE	E	DON	90.27
21-Oct-2016 06:44:36	1,975	0	263902	03-018-009	Replace Nut - Wheel, Outer	31-Oct-2016 16:45:45	LAVSHP	I	DON	95.19
21-Oct-2016 06:44:36	1,975	0	263902	06-017-001	Inspect Tire - Pneumatic	24-Oct-2016 12:21:52	LAVSHP	I	DON	21.62
21-Oct-2016 06:44:36	1,975	0	263902	06-100-007	Inspect In-Service Inspection	21-Oct-2016 08:42:30	LAVSHP	P	DON	64.43
24-Apr-2015 13:42:5	1,910	0	207644	24-065-004	Repair Cylinder	24-Apr-2015 13:43:30	BYLOFC	O	DON	292.89
09-Nov-2012 15:30:2	394	0	102211	24-017-001	Repair Tire - Pneumatic	09-Nov-2012 15:31:39	BTIRE	F	DON	297.04
24-Apr-2015 13:21:5	1,910	0	207637	24-065-004	Repair Cylinder	24-Apr-2015 13:24:37	BYLOFC	O	DON	525.34
19-Aug-2014 06:00:00	1,897	0	171897	24-305	Repair Trencher	19-Aug-2014 17:00:00	LAKEVL	B	DON	27.74
19-Aug-2014 06:00:00	1,897	0	171897	26-305	Weld Trencher	19-Aug-2014 17:00:00	LAKEVL	B	DON	27.74
10-Dec-2015 07:29:5	1,968	0	227668	24-017-001	Repair Tire - Pneumatic	10-Dec-2015 07:30:17	BTIRE	E	DON	116.96
16-Jan-2012 12:53:23	1,696	0	92958	06-100-PMB	Inspect B PMI	16-Jan-2012 12:56:51	BYLOFC	P	DON	55.48
16-Jan-2012 12:53:23	1,696	0	92958	26-305	Weld Trencher	16-Jan-2012 13:00:17	BYLOFC	I	DON	83.22
05-Feb-2016 15:24:17	1,969	0	232353	24-065-004	Repair Cylinder	22-Feb-2016 07:28:17	LAVSHP	I	DON	1,064.40
16-Nov-2016 11:37:1	2,000	0	271558	03-017-001	Replace Tire - Pneumatic	16-Nov-2016 11:37:27	BTIRE	F	DON	1,868.34

Unit Job History

Michels Corporation
Report Printed: 17-Nov-2020 11:57:22 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: H0412 - 2003 CASE 960										
06-Sep-2013 00:00:00	394	0	130814	03-063-003	Replace Transceiver - GPS Tracker	06-Sep-2013 00:00:00	BURNSV	C	DON	244.35
16-Jan-2012 12:53:23	1,696	0	92958	03-044-002	Replace Filters	16-Jan-2012 12:58:42	BYLOFC	P	DON	27.74
05-Aug-2016 14:54:5	1,975	0	255731	11-065-011	Rebuild Motor - Piston Type	05-Oct-2016 08:06:17	LAVSHP	B	DON	523.01
15-Apr-2013 06:41:4	394	0	118501	24-017-001	Repair Tire - Pneumatic	15-Apr-2013 06:42:02	BTIRE	F	DON	114.34
03-May-2016 15:02:5	1,970	0	243332	06-100-PMMA	Inspect A PMI		LAVSHP	P	CAN	0.00
03-May-2016 15:02:5	1,970	0	243332	06-325	Inspect Cable Plow	04-May-2016 13:56:10	LAVSHP	P	DON	61.77
07-Nov-2013 07:17:4	394	0	136164	24-017-001	Repair Tire - Pneumatic	07-Nov-2013 07:18:03	BTIRE	E	DON	38.50
06-Aug-2012 10:58:0	394	0	97727	24-017-001	Repair Tire - Pneumatic	06-Aug-2012 10:58:29	BTIRE	F	DON	72.86
20-Dec-2016 17:17:0	2,000	0	270475	03-013-030	Replace Switch - Parking Brake	21-Dec-2016 06:44:42	LAVSHP	B	DON	59.10
10-Nov-2015 00:00:0	1,968	0	229980	24-305	Repair Trencher	10-Nov-2015 00:00:00	LAVSHP	I	DON	15.45
05-Nov-2018 10:44:4	2,006	0	359489	14-310	Install Backhoe (Rubber Tire)	05-Nov-2018 14:44:53	BSMEQP	Z	DON	158.52
15-Nov-2013 06:00:0	394	0	139957	03-065-003	Replace Cooler - Oil (Heat Exchanger)	18-Nov-2013 17:00:00	LAKEVL	F	DON	105.05
10-Nov-2015 00:00:0	1,968	0	229980	03-065-023	Replace Holding Valve	10-Nov-2015 00:00:00	LAVSHP	B	DON	30.91
10-Nov-2015 00:00:0	1,968	0	229980	03-325-003	Replace Shaker Box / Vibrator	10-Nov-2015 00:00:00	LAVSHP	B	DON	139.09
17-Jun-2015 08:42:15	1,953	0	208765	03-325-003	Replace Shaker Box / Vibrator	17-Jun-2015 09:43:23	LAVOFC	N	DON	246.18

Unit No: H0412

Count: 44

16,798.94