

Unit Job History

Michels Corporation
Report Printed: 18-Aug-2020 08:50:54 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0700 - 2011 JOHN DEERE 350G										
05-Jan-2014 06:00:00	2,030	0	160519	03-002-024	Replace Glass / Windshield	05-Jan-2014 17:00:00	U31015	B	DON	73.65
29-Jul-2014 06:00:00	2,973	0	174054	06-330	Inspect Excavator	29-Jul-2014 17:00:00	BYLOFC	F	DON	2,339.19
14-Sep-2013 13:28:11	1,281	0	132426	07-100-300	Lubricate Off Road Equip / Field Service	14-Sep-2013 13:28:13	U31015	P	DON	73.77
04-Oct-2011 09:33:12	7	0	74018	14-003-005	Install Anti-Theft Device	04-Oct-2011 10:22:59	BHVVYEQ	C	DON	426.52
25-Apr-2017 07:26:31	4,308	0	286368	26-330-012	Weld Counter Weight Assembly	01-May-2017 06:12:08	BHVVYEQ	N	DON	226.73
20-Feb-2014 06:00:00	2,219	0	152441	03-002-035	Replace Windshield Wiper & Washer	01-May-2014 14:52:00	U31015	O	DON	125.22
20-Feb-2014 06:00:00	2,219	0	152441	03-065-004	Replace Cylinder	01-May-2014 14:52:00	U31015	O	DON	0.00
20-Feb-2014 06:00:00	2,219	0	152441	03-065-007	Replace Hoses & Fittings	01-May-2014 14:52:00	U31015	O	DON	971.12
20-Feb-2014 06:00:00	2,219	0	152441	24-330-001	Repair Bucket and Attachments	01-May-2014 14:52:00	U31015	B	DON	6,629.48
31-Jul-2018 11:55:27	4,343	0	346153	03-065-008	Replace Line / Tubing Assembly	31-Jul-2018 14:16:17	70955W	B	DON	406.33
27-Mar-2012 16:01:5	330	0	95603	03-044-002	Replace Filters	27-Mar-2012 16:05:10	BYLOFC	P	DON	495.74
27-Mar-2012 16:01:5	330	0	95603	06-100-PMB	Inspect B PMI	27-Mar-2012 16:03:57	BYLOFC	P	DON	318.62
06-Aug-2013 00:00:0	1,068	0	127364	03-063-003	Replace Transceiver - GPS Tracker	06-Aug-2013 00:00:00	BHVVYEQ	C	DON	244.35
05-Sep-2013 10:59:30	1,068	0	136877	03-045-023	Replace Engine Belts	05-Sep-2013 11:01:05	BYLOFC	P	DON	528.67
05-Sep-2013 10:59:30	1,068	0	136877	06-100-007	Inspect In-Service Inspection	05-Sep-2013 11:01:05	BYLOFC	P	DON	618.63
15-Jun-2016 09:51:18	3,578	0	248645	03-111-002	Replace Roller	21-Jun-2016 13:06:49	U60950	F	DON	746.93
15-Jun-2016 09:51:18	3,578	0	248645	03-514-002	Replace Shanks or Teeth	21-Jun-2016 13:06:49	U60950	F	DON	1,162.22
20-Apr-2020 14:44:1	5,085	0	436870	03-045-011	Replace Filter Assembly - Oil	22-Apr-2020 12:34:55	HARSHP	I	DON	1,731.44
01-Apr-2016 10:02:5	3,407	0	239725	02-330	Clean Excavator	20-Apr-2016 05:43:03	BWASH	J	DON	802.02
01-Apr-2016 10:02:5	3,407	0	239725	03-002-026	Replace Weather Stripping, Gaskets & B	18-May-2016 13:32:02	BHVVYEQ	I	DON	68.68
01-Apr-2016 10:02:5	3,407	0	239725	03-044-018	Replace Fuel Hose / Line	18-May-2016 13:32:16	BHVVYEQ	I	DON	770.01
01-Apr-2016 10:02:5	3,407	0	239725	06-100-PMB	Inspect B PMI	18-May-2016 13:37:28	BHVVYEQ	P	DON	1,523.70
01-Apr-2016 10:02:5	3,407	0	239725	06-330	Inspect Excavator	18-May-2016 13:27:37	BHVVYEQ	J	DON	396.99
01-Apr-2016 10:02:5	3,407	0	239725	06-330-002	Inspect Undercarriage (Tracks&Rollers)	06-Apr-2016 05:10:18	BHVVYEQ	J	DON	131.63
01-Apr-2016 10:02:5	3,407	0	239725	24-063-003	Repair Transceiver - GPS Tracker	18-Apr-2016 14:43:46	BHVVYEQ	Q	DON	1,028.70

Unit Job History

Michels Corporation
Report Printed: 18-Aug-2020 08:50:54 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Job Total Cost
Unit No: N0700 - 2011 JOHN DEERE 350G										
01-Apr-2016 10:02:5	3,407	0	239725	24-065-008	Repair Line / Tubing Assembly	18-May-2016 13:33:49	BHVYEQ	I	DON	556.70
01-Apr-2016 10:02:5	3,407	0	239725	34-043-002	Reseal Exhaust Manifold	18-May-2016 13:34:50	BHVYEQ	I	DON	4,052.83
01-Apr-2016 10:02:5	3,407	0	239725	34-065-005	Reseal Drive - Motor / Pump	18-May-2016 13:31:15	BHVYEQ	I	DON	2,119.20
10-Dec-2013 06:00:0	1,914	0	156227	06-100-PMB	Inspect B PMI	10-Dec-2013 17:00:00	U31015	P	DON	147.30
10-Dec-2013 06:00:0	1,914	0	156227	07-100-300	Lubricate Off Road Equip / Field Service	10-Dec-2013 17:00:00	U31015	P	DON	36.83
12-Dec-2016 05:29:2	3,824	0	269293	02-330	Clean Excavator	12-Dec-2016 07:55:23	BWASH	J	DON	64.78
01-Aug-2013 13:54:4	2,672	0	160945	03-330-001	Replace Bucket and Attachments	09-Jun-2014 14:05:15	U31015	O	DON	846.05
01-Aug-2013 13:54:4	2,672	0	160945	03-330-002	Replace Undercarriage (Tracks&Rollers)	09-Jun-2014 14:05:15	U31015	O	DON	574.56
01-Aug-2013 13:54:4	2,672	0	160945	06-100-007	Inspect In-Service Inspection	09-Jun-2014 14:05:15	U31015	P	DON	2,548.51
15-Jan-2014 06:00:00	2,148	0	158940	06-100-PMB	Inspect B PMI	15-Jan-2014 17:00:00	U31015	P	DON	147.30
04-Apr-2014 08:42:2	2,462	0	161847	03-002-010	Replace Mirrors	04-Apr-2014 08:43:14	BVLOFC	F	DON	407.54
04-Apr-2014 08:42:2	2,462	0	161847	24-002-012	Repair Floor Pan	04-Apr-2014 08:43:14	BVLOFC	F	DON	362.91
04-Apr-2014 08:42:2	2,462	0	161847	24-034	Repair Lighting System	04-Apr-2014 08:43:14	BVLOFC	F	DON	711.46
04-Apr-2014 08:42:2	2,462	0	161847	24-330	Repair Excavator	04-Apr-2014 08:43:14	BVLOFC	F	DON	519.88
08-Jul-2017 04:48:41	4,308	0	295991	14-051-009	Install Fire Extinguisher	08-Jul-2017 04:48:57	BHVYEQ	Q	DON	98.54
01-Aug-2017 12:53:4	4,343	0	299094	03-045-014	Replace Ventilating System	02-Aug-2017 12:00:01	BHVYEQ	I	DON	1,556.16
01-Aug-2017 12:53:4	4,343	0	299094	03-054-002	Replace Alarm - Reverse Signal	03-Aug-2017 06:35:56	BHVYEQ	I	DON	306.81
01-Aug-2017 12:53:4	4,343	0	299094	06-100-PMA	Inspect A PMI	03-Aug-2017 06:36:03	BHVYEQ	P	DON	105.47
01-Aug-2017 12:53:4	4,343	0	299094	26-330-002	Weld Undercarriage (Tracks&Rollers)	02-Aug-2017 10:10:41	BHVYEQ	I	DON	79.47
06-Dec-2016 16:20:1	3,824	0	268822	03-330-002	Replace Undercarriage (Tracks&Rollers)	10-Dec-2016 09:24:41	BHVYEQ	N	DON	429.24
06-Dec-2016 16:20:1	3,824	0	268822	06-100-PMB	Inspect B PMI	10-Dec-2016 09:25:04	BHVYEQ	P	DON	1,215.76
21-Oct-2013 06:00:00	1,575	0	138137	03-001-016	Replace Filter - Cab Ventilation	21-Oct-2013 17:00:00	U31015	P	DON	36.83
21-Oct-2013 06:00:00	1,575	0	138137	03-044-002	Replace Filters	21-Oct-2013 17:00:00	U31015	P	DON	36.83
21-Oct-2013 06:00:00	1,575	0	138137	03-044-024	Replace Fuel / Water Separator	21-Oct-2013 17:00:00	U31015	P	DON	36.83
21-Oct-2013 06:00:00	1,575	0	138137	06-100-PMB	Inspect B PMI	21-Oct-2013 17:00:00	U31015	P	DON	73.65
01-May-2014 05:27:3	2,972	0	166562	03-044-013	Replace Cap - Fuel Tank	24-Jul-2014 05:36:18	U31015	O	DON	89.95
01-May-2014 05:27:3	2,972	0	166562	03-065-007	Replace Hoses & Fittings	24-Jul-2014 05:36:18	U31015	I	DON	446.63
01-May-2014 05:27:3	2,972	0	166562	06-100-007	Inspect In-Service Inspection	24-Jul-2014 05:36:18	U31015	P	DON	915.90
04-Jun-2015 17:03:15	2,981	0	203141	03-002-021	Replace Panel - Rear Door	01-Jul-2015 06:38:38	BHVYEQ	E	DON	3,682.05

Unit Job History

Michels Corporation
Report Printed: 18-Aug-2020 08:50:54 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0700 - 2011 JOHN DEERE 350G										
04-Jun-2015 17:03:15	2,981	0	203141	03-042-014	Replace Coolant Overflow Reservoir	01-Jul-2015 06:44:04	BHVYEQ	I	DON	358.65
04-Jun-2015 17:03:15	2,981	0	203141	03-045-026	Replace Tensioner - Engine Belts	01-Jul-2015 06:50:49	BHVYEQ	I	DON	885.43
04-Jun-2015 17:03:15	2,981	0	203141	03-111-002	Replace Roller	01-Jul-2015 06:43:10	BHVYEQ	I	DON	1,588.44
04-Jun-2015 17:03:15	2,981	0	203141	06-100-PMA	Inspect A PMI	01-Jul-2015 06:44:10	BHVYEQ	P	DON	346.72
04-Jun-2015 17:03:15	2,981	0	203141	06-330	Inspect Excavator	01-Jul-2015 06:57:04	BHVYEQ	I	DON	2,826.78
04-Jun-2015 17:03:15	2,981	0	203141	24-002-021	Repair Panel - Rear Door	01-Jul-2015 06:41:38	BHVYEQ	E	DON	563.09
04-Jun-2015 17:03:15	2,981	0	203141	24-034-001	Repair Headlamps / Fog Lamps	01-Jul-2015 06:42:39	BHVYEQ	I	DON	251.01
04-Jun-2015 17:03:15	2,981	0	203141	24-518-001	Repair Steps	01-Jul-2015 06:37:51	BHVYEQ	E	DON	485.57
30-Jun-2016 17:03:51	3,824	0	250489	03-044-002	Replace Filters	30-Jul-2016 09:37:02	U60950	F	DON	231.62
30-Jun-2016 17:03:51	3,824	0	250489	03-072-006	Replace Door Latch Mechanism	30-Jul-2016 09:37:02	U60950	F	DON	47.48
30-Jun-2016 17:03:51	3,824	0	250489	06-100-PMB	Inspect B PMI	30-Jul-2016 09:37:02	U60950	F	DON	57.48
28-Nov-2017 00:00:00	4,343	0	314647	06-100-PMA	Inspect A PMI	28-Nov-2017 00:00:00	BVLOFC	P	DON	0.00
28-Nov-2013 00:00:00	1,633	0	149892	24-330-002	Repair Undercarriage (Tracks&Rollers)	28-Nov-2013 00:00:00	U31015	B	DON	1,344.56
17-Jul-2017 11:28:38	4,308	0	297033	02-330	Clean Excavator	18-Jul-2017 10:35:21	BWASH	J	DON	328.80
17-Jul-2017 11:28:38	4,308	0	297033	12-330-012	Refinish Counter Weight Assembly	31-Jul-2017 11:07:27	BSETUP	J	DON	385.94
17-Jul-2017 11:28:38	4,308	0	297033	15-330-012	Paint Prep Counter Weight Assembly	01-Aug-2017 14:54:13	BSETUP	J	DON	691.26
19-Nov-2013 14:08:11	1,633	0	143667	24-410-003	Repair Wiring	19-Nov-2013 14:10:48	BVLOFC	F	DON	910.61
18-Dec-2013 00:00:00	1,829	0	149901	03-MSC	Replace Miscellaneous	18-Dec-2013 00:00:00	U31015	B	DON	1,319.41
13-Dec-2011 16:08:44	56	0	77887	24-065-004	Repair Cylinder	13-Dec-2011 16:14:05	BHVYEQ	O	DON	276.23
06-Mar-2013 14:18:11	802	0	123509	03-044-021	Replace Seal / O-ring	06-Mar-2013 14:19:00	BVLOFC	F	DON	1,031.35
18-Jul-2013 07:22:56	1,056	0	124274	38-100-PMB	Service B PMI	22-Jul-2013 10:28:48	BHVYEQ	P	DON	2,669.41
11-Sep-2013 06:00:00	1,255	0	151282	24-330	Repair Excavator	11-Sep-2013 17:00:00	U31015	F	DON	147.30
17-Aug-2013 06:00:00	1,083	0	151280	24-330	Repair Excavator	17-Aug-2013 17:00:00	U31015	F	DON	147.30
09-Sep-2013 06:00:00	1,231	0	157288	03-051-009	Replace Fire Extinguisher	09-Sep-2013 17:00:00	U31015	F	DON	0.00
31-Aug-2015 10:57:00	3,128	0	214318	24-001-010	Repair Compressor Assembly - Air Cond	31-Aug-2015 10:57:55	BVLOFC	O	DON	908.36
15-Dec-2015 10:08:22	3,339	0	225442	06-100-PMA	Inspect A PMI	16-Dec-2015 06:14:36	BHVYEQ	P	DON	1,292.56
18-Aug-2016 11:24:44	3,824	0	256144	06-043-009	Inspect Diesel Particulate Filter - DPF	18-Aug-2016 12:03:23	U60950	F	DON	467.61
27-Jan-2017 11:06:18	4,308	0	275152	03-528	Replace Bushing	03-Feb-2017 05:38:27	BHVYEQ	N	DON	4,493.01
27-Jan-2017 11:06:18	4,308	0	275152	24-072-006	Repair Door Latch Mechanism	02-Feb-2017 08:27:06	BHVYEQ	N	DON	315.03

Unit Job History

Michels Corporation
 Report Printed: 18-Aug-2020 08:50:54 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: N0700 - 2011 JOHN DEERE 350G										
27-Jan-2017 11:06:18	4,308	0	275152	03-518	Replace Step / Ladder / Carwalk	02-Feb-2017 09:53:26	BHVYEQ	J	DON	218.98
27-Jan-2017 11:06:18	4,308	0	275152	03-002-010	Replace Mirrors	03-Feb-2017 05:36:05	BHVYEQ	I	DON	70.93
27-Jan-2017 11:06:18	4,308	0	275152	06-100-PMA	Inspect A PMI	03-Feb-2017 10:48:48	BHVYEQ	P	DON	478.31

Unit No: N0700

Count: 90

70,982.42