

Unit Job History

Michels Corporation
Report Printed: 22-Mar-2019 08:22:17 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1132 - 2012 CAT 972										
16-Jan-2018 06:11:53	6,142	0	319616	03-065-007	Replace Hoses & Fittings	19-Jan-2018 15:07:12	BHVVYEQ	O	DON	755.62
28-Oct-2013 16:40:57	18	0	135201	38-100-PMB	Service B PMI	28-Oct-2013 16:41:50	BHVVYEQ	J	DON	267.02
29-Oct-2013 12:16:35	966	0	135277	24-001-001	Repair Air Conditioning Assembly	29-Oct-2013 12:19:48	BHVVYEQ	W	DON	533.94
21-Jan-2014 10:08:34	1,651	0	143792	02-002	Clean Cab & Sheet Metal	23-Jan-2014 08:15:23	BHVVYEQ	J	DON	0.00
21-Jan-2014 10:08:34	1,651	0	143792	02-360	Clean Loader / Skid-Steer	22-Jan-2014 12:15:20	BWASH	J	DON	50.33
21-Jan-2014 10:08:34	1,651	0	143792	03-063-003	Replace Transceiver - GPS Tracker	21-Jan-2014 15:37:35	BHVVYEQ	C	DON	87.71
21-Jan-2014 10:08:34	1,651	0	143792	06-100-301	Inspect Annual Service	21-Jan-2014 15:39:42	BHVVYEQ	J	DON	62.69
21-Jan-2014 10:08:34	1,651	0	143792	31-360-009	Rotate Bucket Tooth / Cutting Edge	22-Jan-2014 09:17:36	BHVVYEQ	J	DON	123.09
21-Jan-2014 10:08:34	1,651	0	143792	38-100-PMMA	Service A PMI	22-Jan-2014 09:17:48	BHVVYEQ	J	DON	1,127.79
12-Jan-2017 11:54:34	5,806	0	292476	03-065-007	Replace Hoses & Fittings	12-Jun-2017 17:30:11	BHVVYEQ	I	DON	1,243.63
18-Feb-2017 07:05:33	5,806	0	277780	02-360	Clean Loader / Skid-Steer	20-Feb-2017 15:20:02	BWASH	J	DON	358.76
28-Jun-2018 13:39:28	7,120	0	341852	24-015	Repair Steering	02-Jul-2018 05:56:29	BHVVYEQ	I	DON	1,179.22
12-Mar-2018 05:28:2	6,323	0	326856	03-065-002	Replace Accumulator	15-Mar-2018 13:48:25	BHVVYEQ	I	DON	2,049.27
12-Mar-2018 05:28:2	6,323	0	326856	06-100-PMC	Inspect C PMI	15-Mar-2018 13:48:21	BHVVYEQ	P	DON	2,632.71
12-Mar-2018 05:28:2	6,323	0	326856	06-360	Inspect Loader / Skid-Steer	22-Mar-2018 04:43:11	BHVVYEQ	J	DON	335.04
12-Mar-2018 05:28:2	6,323	0	326856	24-518-001	Repair Steps	15-Mar-2018 13:48:23	BHVVYEQ	I	DON	217.57
19-Jun-2017 13:12:06	6,142	0	293495	24-049-004	Repair ECM Sensor	31-Jul-2017 18:02:23	BHVVYEQ	J	DON	2,578.71
21-Apr-2015 15:05:14	3,252	0	198515	03-027-040	Replace Tube/Line	21-Apr-2015 15:43:01	BHVVYEQ	G	DON	537.60
21-Apr-2015 15:05:14	3,252	0	198515	03-360-008	Replace Operator Controls	21-Apr-2015 15:40:54	BHVVYEQ	G	DON	0.00
08-Dec-2014 13:14:21	3,252	0	183768	03-360-009	Replace Bucket Tooth / Cutting Edge	29-Dec-2014 07:41:15	BHVVYEQ	I	DON	1,475.72
08-Dec-2014 13:14:21	3,252	0	183768	06-100-PMMA	Inspect A PMI	29-Dec-2014 07:42:51	BHVVYEQ	P	DON	0.00
08-Dec-2014 13:14:21	3,252	0	183768	06-100-PMB	Inspect B PMI	29-Dec-2014 07:42:47	BHVVYEQ	P	DON	879.56
08-Dec-2014 13:14:21	3,252	0	183768	06-100-PMC	Inspect C PMI	29-Dec-2014 07:42:44	BHVVYEQ	P	DON	155.64
08-Dec-2014 13:14:21	3,252	0	183768	06-360	Inspect Loader / Skid-Steer	29-Dec-2014 07:41:27	BHVVYEQ	J	DON	21.32
30-Jan-2018 16:12:00	6,312	0	324221	24-017-001	Repair Tire - Pneumatic	30-Jan-2018 16:12:00	BTIRE	F	DON	557.55
17-Feb-2016 12:23:47	5,076	0	233735	24-514	Repair Bucket	22-Feb-2016 09:56:10	BWEED	N	DON	554.06
29-Jul-2015 10:57:22	4,275	0	209477	03-002-024	Replace Glass / Windshield	06-Aug-2015 10:07:41	BHVVYEQ	E	DON	1,161.26
29-Jul-2015 10:57:22	4,275	0	209477	38-100-PMB	Service B PMI	06-Aug-2015 13:20:14	BHVVYEQ	P	DON	827.99
18-Jul-2016 09:23:04	5,500	0	252230	24-065-008	Repair Line / Tubing Assembly	18-Jul-2016 17:30:55	BHVVYEQ	J	DON	812.39

Unit Job History

Michels Corporation
Report Printed: 22-Mar-2019 08:22:17 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1132 - 2012 CAT 972										
16-Dec-2014 14:04:2	2.210	0	184858	02-360	Clean Loader / Skid-Steer	17-Dec-2014 13:29:11	BWASH	J	DON	139.32
16-Dec-2014 14:04:2	2.210	0	184858	24-017-001	Repair Tire - Pneumatic	16-Dec-2014 14:05:45	BTIRE	I	DON	427.95
30-Jul-2014 14:15:18	2.210	0	167359	03-049-004	Replace ECM Sensor	30-Jul-2014 14:15:41	BHVEEQ	W	DON	246.43
22-May-2017 08:28:5	5.806	0	289814	03-052-005	Replace Transmitter - CB	22-May-2017 08:30:04	BHVEEQ	I	DON	23.55
21-May-2014 13:16:1	1.651	0	158806	38-100-PMA	Service A PMI	21-May-2014 13:16:32	BHVEEQ	J	DON	523.11
21-Jul-2018 09:19:44	7.120	0	344838	24-017-001	Repair Tire - Pneumatic	21-Jul-2018 09:19:56	BTIRE	F	DON	828.07
17-Sep-2018 16:17:36	7.120	0	352441	03-094	Replace Lines, Tubes, Hoses & Fittings -	17-Sep-2018 16:18:23	BHVEEQ	I	DON	2,732.52
17-Sep-2018 16:17:36	7.120	0	352441	24-360-008	Repair Operator Controls	17-Sep-2018 16:19:21	BHVEEQ	I	DON	635.01
20-Aug-2014 12:02:1	2.210	0	169871	24-017-001	Repair Tire - Pneumatic	20-Aug-2014 12:02:33	BTIRE	E	DON	541.43
03-Nov-2017 17:31:4	6.142	0	311391	03-049-004	Replace ECM Sensor	07-Nov-2017 14:05:16	BHVEEQ	I	DON	273.86
03-Nov-2017 17:31:4	6.142	0	311391	06-044-002	Inspect Filters	06-Nov-2017 05:52:58	BHVEEQ	J	DON	160.77
15-May-2013 08:08:1	18	0	116810	38-100-001	Service DO NOT USE - PMI Service	15-May-2013 08:08:36	BHVEEQ	J	DON	292.40
29-Dec-2018 07:39:2	7.453	0	366231	06-100-PMA	Inspect A PMI	02-Jan-2019 08:31:37	BHVEEQ	P	DON	1,077.13
25-Oct-2016 11:58:36	5.796	0	264442	24-063-003	Repair Transceiver - GPS Tracker	25-Oct-2016 12:08:28	GPSINS	Q	DON	4.98
08-Feb-2017 14:25:1	5.806	0	276605	24-063-003	Repair Transceiver - GPS Tracker	08-Feb-2017 14:25:26	BHVEEQ	I	DON	29.80
09-Jun-2014 14:50:26	2.210	0	160964	38-100-PMB	Service B PMI	12-Jun-2014 05:51:18	BHVEEQ	J	DON	322.19
30-Oct-2015 10:40:0	4.595	0	220299	06-100-PMA	Inspect A PMI	30-Oct-2015 11:00:20	BHVEEQ	P	DON	1,010.00
15-Sep-2014 06:00:06	2.210	0	176289	38-041-001	Service Air Cleaner	15-Sep-2014 17:00:00	C00050	P	DON	13.50
19-Aug-2015 14:21:4	4.275	0	212373	03-017-001	Replace Tire - Pneumatic	19-Aug-2015 14:22:08	BTIRE	F	DON	360.60
22-Nov-2016 13:54:5	5.806	0	267553	02-002	Clean Cab & Sheet Metal	28-Nov-2016 08:39:05	BHVEEQ	J	DON	61.65
22-Nov-2016 13:54:5	5.806	0	267553	03-094	Replace Lines, Tubes, Hoses & Fittings -	30-Nov-2016 15:56:16	BHVEEQ	I	DON	1,627.48
22-Nov-2016 13:54:5	5.806	0	267553	06-100-PMB	Inspect B PMI	10-Dec-2016 09:48:13	BHVEEQ	P	DON	943.96
22-Nov-2016 13:54:5	5.806	0	267553	06-100-PMC	Inspect C PMI	30-Nov-2016 15:55:27	BHVEEQ	P	DON	411.64
22-Nov-2016 13:54:5	5.806	0	267553	06-360	Inspect Loader / Skid-Steer	23-Nov-2016 05:42:04	BHVEEQ	P	DON	166.13
22-Nov-2016 13:54:5	5.806	0	267553	24-052-013	Repair Antenna and Mounting	28-Nov-2016 08:46:27	BHVEEQ	I	DON	82.65
22-Nov-2016 13:54:5	5.806	0	267553	24-063-003	Repair Transceiver - GPS Tracker	28-Nov-2016 10:49:35	BHVEEQ	W	DON	339.59
22-Nov-2016 13:54:5	5.806	0	267553	31-360-009	Rotate Bucket Tooth / Cutting Edge	30-Nov-2016 15:54:53	BHVEEQ	I	DON	218.16
15-Aug-2017 09:07:1	6.142	0	301060	06-049-001	Inspect ECM Fault Code	15-Aug-2017 09:07:37	BHVEEQ	I	DON	744.97
02-Mar-2018 10:22:4	6.312	0	325783	02-360	Clean Loader / Skid-Steer	05-Mar-2018 08:10:33	BWASH	J	DON	241.38

Unit Job History

Michels Corporation
Report Printed: 22-Mar-2019 08:22:17 By User: RHEINNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: P1132 - 2012 CAT 972										
14-Aug-2013 14:21:5	18	0	127101	38-100-001	Service DO NOT USE - PMI Service	14-Aug-2013 14:22:26	BHVEEQ	J	DON	405.98
13-Feb-2016 06:22:56	5,076	0	233291	03-043-009	Replace Diesel Particulate Filter	16-Feb-2016 10:17:22	BHVEEQ	J	DON	3,462.29
13-Feb-2016 06:22:56	5,076	0	233291	03-360-009	Replace Bucket Tooth / Cutting Edge	16-Feb-2016 15:18:14	BHVEEQ	I	DON	1,191.07
13-Feb-2016 06:22:56	5,076	0	233291	06-100-PMB	Inspect B PMI	17-Feb-2016 06:00:29	BHVEEQ	P	DON	1,632.83
13-Feb-2016 06:22:56	5,076	0	233291	24-002-035	Repair Windshield Wiper & Washer	15-Feb-2016 15:39:10	BHVEEQ	I	DON	63.54
06-Sep-2018 15:35:56	7,120	0	351138	06-100-PMMA	Inspect A PMI	06-Sep-2018 15:36:12	BHVEEQ	P	DON	905.54
22-Sep-2015 06:17:36	4,275	0	215608	03-065-007	Replace Hoses & Fittings	22-Sep-2015 09:55:30	BHVEEQ	O	DON	484.97
20-May-2015 14:44:4	3,252	0	201722	24-017-001	Repair Tire - Pneumatic	20-May-2015 14:45:21	BTIRE	F	DON	510.33
25-Jan-2013 14:06:43	18	0	105705	14-063-003	Install Transceiver - GPS Tracker	28-Jan-2013 15:00:00	BHVEEQ	J	DON	635.92
25-Jan-2013 14:06:43	18	0	105705	14-930	Install Scale	31-Jan-2013 09:39:29	BHVEEQ	C	DON	6,691.07
23-Jun-2016 14:49:05	5,500	0	249436	03-065-007	Replace Hoses & Fittings	23-Jun-2016 14:49:23	BHVEEQ	O	DON	1,084.27
23-May-2018 06:41:0	6,400	0	340091	24-017-001	Repair Tire - Pneumatic	23-May-2018 06:42:00	BTIRE	F	DON	410.19
03-May-2016 15:05:4	5,342	0	243333	38-100-PMMA	Service A PMI	03-May-2016 15:05:58	BHVEEQ	J	DON	1,547.29
10-Mar-2016 09:20:1	5,076	0	236804	12-360-001	Refinish Bucket and Attachments	10-Mar-2016 12:15:01	BSETUP	J	DON	256.53
10-Mar-2016 09:20:1	5,076	0	236804	15-360-001	Paint Prep Bucket and Attachments	10-Mar-2016 10:52:55	BSETUP	J	DON	101.83
12-Jan-2015 13:40:23	3,252	0	187365	24-514-003	Repair Liner	14-Jan-2015 13:56:15	BWELD	N	DON	2,799.35
06-Feb-2014 13:36:12	1,651	0	146029	35-013	Diagnose Brakes	06-Feb-2014 13:37:35	BHVEEQ	F	DON	347.69
24-Jan-2013 16:30:48	0	0	105637	14-052-003	Install Radio Equipment	24-Jan-2013 19:14:56	BBODY	C	DON	985.29
13-Mar-2019 13:08:0	7,603	0	376502	25-052-003	Remove Radio Equipment	14-Mar-2019 09:36:47	BHVEEQ	Z	DON	243.42
13-Mar-2019 13:08:0	7,603	0	376502	25-063-003	Remove Transceiver - GPS Tracker	15-Mar-2019 06:41:19	BHVEEQ	Z	DON	0.00
15-Mar-2019 14:09:5	7,603	0	376847	02-360	Clean Loader / Skid-Steer	18-Mar-2019 13:36:31	BWASH	Z	DON	218.53

Unit No: P1132

Count: 79

59,044.35