

# Unit Job History

Michels Corporation  
 Report Printed: 08-Apr-2019 04:18:23 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Job Total Cost
<b>Unit No: A0954 - 1975 MACK MIXER</b>										
09-Jan-2019 09:41:51	63.328	3.598	367503	25-064	Remove Mobile Generator / Gensets	10-Jan-2019 06:39:15	BTRUCK	I	DON	207.52
09-Jan-2019 09:41:51	63.328	3.598	367503	25-097	Remove Pump - Product Transfer	10-Jan-2019 06:39:37	BTRUCK	I	DON	74.81
17-Jan-2019 14:25:32	63.328	3.598	368784	02-002	Clean Cab & Sheet Metal	25-Jan-2019 14:51:54	BSETUP	Z	DON	174.59
17-Jan-2019 14:25:32	63.328	3.598	368784	25-053-005	Remove Markings - Vehicle - Decals	25-Jan-2019 16:33:27	BSETUP	Z	DON	128.62
17-Jan-2019 14:25:32	63.328	3.598	368784	25-063-003	Remove Transceiver - GPS Tracker	25-Jan-2019 13:20:10	BSETUP	Z	DON	12.76
04-Oct-2017 06:59:46	6.332	3.593	307456	03-042-007	Replace Coolant Filter	04-Oct-2017 16:01:00	WTNSHP	P	DON	159.17
12-Dec-2016 08:54:33	6.332	0	269329	14-063-003	Install Transceiver - GPS Tracker	12-Dec-2016 10:58:14	BTRUCK	Q	DON	363.18
13-Dec-2016 09:47:51	6.332	3.593	269476	03-063-003	Replace Transceiver - GPS Tracker	13-Dec-2016 10:19:07	GPSINS	Q	DON	493.52
27-Feb-2018 06:32:40	63.324	3.593	325189	02-002	Clean Cab & Sheet Metal	02-Aug-2018 14:34:17	WTNSHP	I	DON	76.42
27-Feb-2018 06:32:40	63.324	3.593	325189	03-013-010	Replace Air Brake Valve	10-Aug-2018 08:53:17	WTNSHP	I	DON	155.92
27-Feb-2018 06:32:40	63.324	3.593	325189	03-032-001	Replace Battery	30-Jul-2018 14:01:34	WTNSHP	I	DON	33.77
27-Feb-2018 06:32:40	63.324	3.593	325189	03-051-009	Replace Fire Extinguisher	02-Aug-2018 06:10:40	WTNSHP	I	DON	53.30
27-Feb-2018 06:32:40	63.324	3.593	325189	03-078-009	Replace Mud Flaps and Hanger Brackets	02-Aug-2018 06:50:00	WTNSHP	I	DON	41.51
27-Feb-2018 06:32:40	63.324	3.593	325189	06-100-DOT	Inspect DOT Federal Inspection	01-Aug-2018 16:00:24	WTNSHP	P	DON	60.11
27-Feb-2018 06:32:40	63.324	3.593	325189	19-034-003	Wire/Rewire Signal Parking, Backup Lan	02-Aug-2018 10:07:45	WTNSHP	I	DON	114.78
27-Feb-2018 06:32:40	63.324	3.593	325189	24-002-035	Repair Windshield Wiper & Washer	02-Aug-2018 11:02:42	WTNSHP	I	DON	28.38
27-Feb-2018 06:32:40	63.324	3.593	325189	24-054-001	Repair Horn & Mounting	02-Aug-2018 12:23:51	WTNSHP	I	DON	30.61
27-Feb-2018 06:32:40	63.324	3.593	325189	38-052	Service Electrical Accessories	18-Jun-2018 10:03:42	WTNSHP	P	DON	501.76
05-Apr-2017 16:41:00	6.332	3.593	284104	02-042-002	Clean Radiator	09-Jun-2017 06:00:00	WTNSHP	I	DON	1,016.56
05-Apr-2017 16:41:00	6.332	3.593	284104	03-002-035	Replace Windshield Wiper & Washer	09-Jun-2017 07:15:46	WTNSHP	I	DON	280.95
05-Apr-2017 16:41:00	6.332	3.593	284104	03-003	Replace Instruments, Gauges, Warning &	09-Jun-2017 06:00:00	WTNSHP	I	DON	983.81
05-Apr-2017 16:41:00	6.332	3.593	284104	03-010-001	Replace All Axles	09-Jun-2017 07:15:46	MPNSHP	I	CAN	0.00
05-Apr-2017 16:41:00	6.332	3.593	284104	03-011-002	Replace King Pin	09-Jun-2017 07:15:46	MPNSHP	I	DON	2,017.57
05-Apr-2017 16:41:00	6.332	3.593	284104	03-013-007	Replace Brake Lines & Fittings - Hydraul	09-Jun-2017 07:15:46	WTNSHP	I	DON	475.15
05-Apr-2017 16:41:00	6.332	3.593	284104	03-015	Replace Steering	09-Jun-2017 06:00:00	WTNSHP	I	DON	912.93
05-Apr-2017 16:41:00	6.332	3.593	284104	03-016-003	Replace Shock Absorber - Front	09-Jun-2017 07:15:46	WTNSHP	I	DON	370.01
05-Apr-2017 16:41:00	6.332	3.593	284104	03-017-001	Replace Tire - Pneumatic	24-May-2017 06:28:58	WTNSHP	I	DON	4,334.25
05-Apr-2017 16:41:00	6.332	3.593	284104	03-032-001	Replace Battery	09-Jun-2017 07:15:46	WTNSHP	I	DON	756.01
05-Apr-2017 16:41:00	6.332	3.593	284104	03-034-002	Replace Stop, Tail, Turn & License	09-Jun-2017 06:00:00	WTNSHP	I	DON	156.39

# Unit Job History

Mitchell Corporation  
Report Printed: 08-Apr-2019 04:18:23 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
<b>Unit No: A0954 - 1975 MACK MIXER</b>										
05-Apr-2017 16:41:00	6.332	3.593	284104	03-044-018	Replace Fuel Hose / Line	09-Jun-2017 07:15:46	MPNSHP	I	DON	518.13
05-Apr-2017 16:41:00	6.332	3.593	284104	03-045-024	Replace Seal - Crankshaft (Front)	09-Jun-2017 07:15:46	MPNSHP	I	DON	704.89
05-Apr-2017 16:41:00	6.332	3.593	284104	03-053-007	Replace Hardware - Expendable Items	09-Jun-2017 07:15:46	MPNSHP	I	DON	1,057.59
05-Apr-2017 16:41:00	6.332	3.593	284104	03-054-001	Replace Horn & Mounting	09-Jun-2017 07:15:46	WTSNHP	I	DON	938.21
05-Apr-2017 16:41:00	6.332	3.593	284104	03-094	Replace Lines, Tubes, Hoses & Fittings -	23-May-2017 11:16:40	WTSNHP	P	DON	293.47
05-Apr-2017 16:41:00	6.332	3.593	284104	06-100-009	Inspect Safety Check	09-Jun-2017 07:15:36	WTSNHP	P	DON	135.50
05-Apr-2017 16:41:00	6.332	3.593	284104	06-100-DOT	Inspect DOT Federal Inspection	09-Jun-2017 06:35:32	WTSNHP	P	DON	377.26
05-Apr-2017 16:41:00	6.332	3.593	284104	14-050	Install Accessories Group		WTSNHP	M	CAN	0.00
05-Apr-2017 16:41:00	6.332	3.593	284104	20-010	Tow Chassis Group	24-May-2017 06:29:13	WTSNHP	B	DON	472.24
05-Apr-2017 16:41:00	6.332	3.593	284104	24-013-009	Repair Air Compressor	09-Jun-2017 07:15:46	WTSNHP	I	DON	398.65
05-Apr-2017 16:41:00	6.332	3.593	284104	24-022	Repair Axles - Driven, Rear	09-Jun-2017 07:15:46	MPNSHP	I	DON	12,733.90
05-Apr-2017 16:41:00	6.332	3.593	284104	24-042-012	Repair Clamps and Hoses	09-Jun-2017 07:15:46	WTSNHP	I	DON	317.84
05-Apr-2017 16:41:00	6.332	3.593	284104	24-064	Repair Mobile Generator / Gensets	05-Apr-2017 00:00:00	BVLOFC	J	DON	1,433.83
05-Apr-2017 16:41:00	6.332	3.593	284104	24-506-001	Repair Fuel Tank	09-Jun-2017 07:15:46	WTSNHP	I	DON	416.87
16-Oct-2017 10:59:20	6.332	3.593	308953	03-032-001	Replace Battery	16-Oct-2017 16:00:37	WTSNHP	P	DON	482.40

Unit No: A0954

Count: 44

34,295.14