

Unit Job History

Mitchels Corporation
Report Printed: 22-Mar-2019 13:02:44 By User: RHENNING

WO Open Date Meter 1 Meter 2 Work Order Job Code Job Description Date Completed Job Location Job Reason Job Status Total Cost

Unit No: B2179 - 2013 F150 SUPERCAB

31-Aug-2018 13:35:3	204,800	0	350637	03-017-001	Replace Tire - Pneumatic	31-Aug-2018 13:35:48	BTRIRE	B	DON	386.07
01-Apr-2013 06:00:00	5,900	0	128896	06-100-001	Inspect DO NOT USE - PMI Service	23-Oct-2013 10:07:32	U31036	F	DON	152.50
01-Apr-2013 06:00:00	5,900	0	128896	06-100-001	Inspect A PMI	23-Oct-2013 10:07:32	U31036	P	DON	0.00
22-Feb-2018 12:11:34	200,535	0	324711	03-032-002	Replace Starter	04-May-2018 13:28:08	BVLOFC	B	DON	722.11
22-Feb-2018 12:11:34	200,535	0	324711	20-010	Tow Chassis Group	04-May-2018 13:28:04	BVLOFC	B	DON	111.71
10-Jun-2015 14:55:43	83,197	0	203837	03-018-001	Replace Front Axle Hubs & Bearings	10-Jun-2015 14:58:19	BVLOFC	O	DON	638.87
10-Jun-2015 14:55:43	83,197	0	203837	03-045-023	Replace Engine Belts	10-Jun-2015 15:21:46	BVLOFC	I	DON	139.59
10-Jun-2015 14:55:43	83,197	0	203837	24-033-003	Repair Spark Plugs	10-Jun-2015 15:01:59	BVLOFC	I	DON	480.02
10-Jun-2015 14:55:43	83,197	0	203837	24-034-004	Repair Clearance & Marker Lamps	10-Jun-2015 15:10:51	BVLOFC	I	DON	53.92
10-Jun-2015 14:55:43	83,197	0	203837	31-017-001	Rotate Tire - Pneumatic	10-Jun-2015 15:03:40	BVLOFC	P	DON	17.77
10-Jun-2015 14:55:43	83,197	0	203837	38-025-001	Service Transfer Case Assembly	10-Jun-2015 15:16:53	BVLOFC	P	DON	114.04
25-Jul-2017 10:31:08	172,547	0	298139	03-017-001	Replace Tire - Pneumatic	01-Aug-2017 12:29:33	HARSHIP	I	DON	966.22
25-Jul-2017 10:31:08	172,547	0	298139	03-041-007	Replace Filter - Outer	25-Jul-2017 14:02:14	BVLOFC	P	DON	23.22
25-Jul-2017 10:31:08	172,547	0	298139	06-100-001	Inspect A PMI	25-Jul-2017 14:12:23	BVLOFC	P	DON	70.89
25-Jul-2017 10:31:08	172,547	0	298139	24-034-002	Repair Stop, Trail, Turn & License	25-Jul-2017 14:00:57	BVLOFC	O	DON	20.67
25-Jul-2017 10:31:08	172,547	0	298139	38-021-103	Service Differential Carrier	25-Jul-2017 14:12:18	BVLOFC	P	DON	158.49
25-Jul-2017 10:31:08	172,547	0	298139	38-022-003	Service Differential Carrier	25-Jul-2017 14:12:12	BVLOFC	P	DON	171.05
23-Feb-2018 06:00:00	195,504	0	325857	35-037	Diagnose Electrical - Modules/Relays	03-Mar-2018 11:01:12	MPNFLD	B	DON	316.22
20-Aug-2013 06:00:00	19,700	0	136885	06-100-001	Inspect B PMI	20-Aug-2013 17:00:00	BVLOFC	P	DON	16.92
06-Aug-2018 10:24:00	204,800	0	346850	24-044	Repair Fuel System	06-Aug-2018 14:35:06	BVLOFC	O	DON	588.33
25-May-2018 08:08:13	204,800	0	337237	06-100-001	Inspect A PMI	12-Jun-2018 09:02:43	HARFLD	P	DON	83.42
16-Dec-2015 09:03:40	118,458	0	225658	03-017-001	Replace Tire - Pneumatic	16-Dec-2015 09:03:55	BTIRE	N	DON	968.93
16-Apr-2015 15:28:34	83,180	0	198171	03-034	Replace Lighting System	20-Apr-2015 15:43:55	BTRUCK	I	DON	52.68
16-Apr-2015 15:28:34	83,180	0	198171	03-045-023	Replace Engine Belts	20-Apr-2015 15:48:32	BTRUCK	I	DON	136.39
16-Apr-2015 15:28:34	83,180	0	198171	15-002	Paint Prep Cab & Sheet Metal	27-Apr-2015 06:51:35	BTRUCK	A	DON	2,833.84
16-Apr-2015 15:28:34	83,180	0	198171	24-018-001	Repair Front Axle Hubs & Bearings	20-Apr-2015 15:21:29	BTRUCK	E	DON	625.93
16-Apr-2015 15:28:34	83,180	0	198171	24-033-003	Repair Spark Plugs	20-Apr-2015 15:23:54	BTRUCK	I	DON	469.03
16-Apr-2015 15:28:34	83,180	0	198171	31-017	Rotate Tires, Tubes, Liners & Valves	20-Apr-2015 15:25:49	BTRUCK	I	DON	17.36
16-Apr-2015 15:28:34	83,180	0	198171	38-025-001	Service Transfer Case Assembly	20-Apr-2015 15:46:26	BTRUCK	I	DON	111.43

Unit Job History

Michels Corporation
Report Printed: 22-Mar-2019 13:02:44 By User: RHEINING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2179 - 2013 F150 SUPERCAB										
11-Apr-2013 07:42:11	0	0	113593	06-100-009	Inspect Safety Check	17-Apr-2013 12:00:34	BTRUCK	P	DON	27.87
11-Apr-2013 07:42:11	0	0	113593	14-052-003	Install Radio Equipment	17-Apr-2013 10:55:51	BBODY	C	DON	1,234.14
11-Apr-2013 07:42:11	0	0	113593	14-052-011	Install Auxiliary Power	16-Apr-2013 16:24:02	BBODY	C	DON	160.10
11-Apr-2013 07:42:11	0	0	113593	14-053-005	Install Markings - Vehicle - Decals	17-Apr-2013 10:16:40	BBODY	J	DON	38.20
11-Apr-2013 07:42:11	0	0	113593	14-053-014	Install Floor Mats	17-Apr-2013 10:37:15	BBODY	C	DON	84.44
11-Apr-2013 07:42:11	0	0	113593	14-063-003	Install Transceiver - GPS Tracker	16-Apr-2013 17:01:14	BBODY	C	DON	319.36
11-Apr-2013 07:42:11	0	0	113593	14-071-011	Install Scuff Liner / Bed Mat	16-Apr-2013 16:19:19	BBODY	C	DON	77.87
11-Apr-2013 07:42:11	0	0	113593	14-078-009	Install Mud Flaps and Hanger Brackets	17-Apr-2013 07:28:59	BBODY	C	DON	108.44
11-Apr-2013 07:42:11	0	0	113593	14-078-014	Install Tarpaulin	17-Apr-2013 08:56:08	BBODY	C	DON	453.05
11-Apr-2013 07:42:11	0	0	113593	14-079-003	Install Strap, Anti-Static	17-Apr-2013 13:17:16	BTRUCK	C	DON	30.55
03-Oct-2017 11:12:07	195,504	0	307350	03-018-001	Replace Front Axle Hubs & Bearings	04-Oct-2017 06:15:33	BVLOFC	O	DON	552.09
03-Oct-2017 11:12:07	195,504	0	307350	06-100-PMA	Inspect A PMI	04-Oct-2017 06:15:36	BVLOFC	P	DON	43.86
03-Oct-2017 11:12:07	195,504	0	307350	24-034-004	Repair Clearance & Marker Lamps	04-Oct-2017 06:15:27	BVLOFC	O	DON	37.65
02-Oct-2013 06:00:00	19,700	0	134731	06-100-PMB	Inspect B PMI	02-Oct-2013 17:00:00	BVLOFC	P	DON	33.84
16-Sep-2013 06:00:00	19,700	0	134817	03-045-011	Replace Filter Assembly - Oil	16-Sep-2013 17:00:00	BVLOFC	F	DON	33.84
01-Oct-2013 06:00:00	19,700	0	135652	03-051-006	Replace Safety Devices	01-Nov-2013 11:19:57	U31036	F	DON	67.94
19-Aug-2013 12:14:0	5,900	0	130230	03-017-001	Replace Tire - Pneumatic	19-Aug-2013 12:14:26	BTTRE	N	DON	1,052.24
04-Feb-2014 06:00:00	19,700	0	147060	03-032-001	Replace Battery	04-Feb-2014 17:00:00	HARRIS	F	DON	13.99
04-Feb-2014 06:00:00	19,700	0	147060	38-032	Service Cranking System	04-Feb-2014 17:00:00	HARRIS	F	DON	55.96
09-Feb-2017 13:44:56	172,547	0	276722	02-032-001	Clean Battery	13-Feb-2017 06:31:08	BVLOFC	P	DON	30.51
09-Feb-2017 13:44:56	172,547	0	276722	03-002-024	Replace Glass / Windshield	13-Feb-2017 06:31:41	BVLOFC	O	DON	335.13
09-Feb-2017 13:44:56	172,547	0	276722	03-002-035	Replace Windshield Wiper & Washer	13-Feb-2017 06:31:22	BVLOFC	O	DON	30.05
09-Feb-2017 13:44:56	172,547	0	276722	03-016-003	Replace Shock Absorber - Front	13-Feb-2017 06:31:27	BVLOFC	I	CAN	0.00
09-Feb-2017 13:44:56	172,547	0	276722	03-016-006	Replace Shock Absorber - Rear	13-Feb-2017 06:31:04	BVLOFC	O	DON	213.57
09-Feb-2017 13:44:56	172,547	0	276722	03-032-001	Replace Battery	13-Feb-2017 06:30:59	BVLOFC	O	DON	145.61
09-Feb-2017 13:44:56	172,547	0	276722	03-033-003	Replace Spark Plugs	13-Feb-2017 06:30:59	BVLOFC	O	DON	358.66
09-Feb-2017 13:44:56	172,547	0	276722	03-034	Replace Lighting System	13-Feb-2017 07:04:27	BVLOFC	O	DON	182.84
09-Feb-2017 13:44:56	172,547	0	276722	03-041-007	Replace Filter - Outter	13-Feb-2017 06:31:12	BVLOFC	P	DON	24.67
09-Feb-2017 13:44:56	172,547	0	276722	06-100-PMA	Inspect A PMI	13-Feb-2017 06:31:46	BTRUCK	P	DON	42.82

Unit Job History

Mitchels Corporation
Report Printed: 22-Mar-2019 13:02:44 By User: RHENNING

WO Open Date	Meter 1	Meter 2	Work Order	Job Code	Job Description	Date Completed	Job Location	Job Reason	Job Status	Total Cost
Unit No: B2179 - 2013 F150 SUPERCAB										
09-Feb-2017 13:44:56	172,547	0	276722	24-002	Repair Cab & Sheet Metal	13-Feb-2017 06:21:03	BVLOFC	O	DON	63.67
09-Feb-2017 13:44:56	172,547	0	276722	38-021-103	Service Differential Carrier	13-Feb-2017 06:31:35	BVLOFC	P	DON	176.45
09-Feb-2017 13:44:56	172,547	0	276722	38-022-003	Service Differential Carrier	13-Feb-2017 07:03:23	BVLOFC	P	DON	193.20
09-Feb-2017 13:44:56	172,547	0	276722	38-025-001	Service Transfer Case Assembly	13-Feb-2017 06:31:18	BVLOFC	P	DON	221.12
09-Feb-2017 13:44:56	172,547	0	276722	38-027-001	Service Case Assembly - Automatic Tran	13-Feb-2017 06:30:55	BVLOFC	P	DON	211.21
09-Mar-2016 12:47:3	118,458	0	236685	03-002-024	Replace Glass / Windshield	20-Apr-2016 13:23:15	HARSHIP	E	DON	284.51
20-Jul-2013 00:00:00	64	0	125505	03-063-003	Replace Transceiver - GPS Tracker	20-Jul-2013 00:00:00	BTRUCK	C	DON	221.49
11-Mar-2019 15:21:5	224,058	0	376163	06-100-009	Inspect Safety Check	12-Mar-2019 13:02:51	BTRUCK	P	DON	43.91
15-Mar-2019 05:37:2	224,058	0	376735	02-002	Clean Cab & Sheet Metal		BSETUP	Z	WND	575.19
15-Mar-2019 05:37:2	224,058	0	376735	12-018-003	Refinish Wheels	21-Mar-2019 15:57:25	BSETUP	Z	DON	51.82
15-Mar-2019 05:37:2	224,058	0	376735	25-052-003	Remove Radio Equipment	21-Mar-2019 17:01:21	BSETUP	Z	DON	20.71
15-Mar-2019 05:37:2	224,058	0	376735	25-053-005	Remove Markings - Vehicle - Decals	18-Mar-2019 08:14:11	BSETUP	Z	DON	24.29
15-Mar-2019 05:37:2	224,058	0	376735	25-063-003	Remove Transceiver - GPS Tracker	18-Mar-2019 07:24:00	BSETUP	Z	DON	42.90

Unit No: B2179

Count: 71

18,369.38